



Telephone: 867-777-8907

Fax: 867-777-2090

April 6, 2017

L.J.'s Septic Services & Contracting Ltd.
P.O. Box 151
Fort McPherson, NT X0E 0J0

Attention: Leslie J Blake

File Number	G16Q001
Type of Operation	QUARRY SITE - Existing
Location	Frog Creek Km 126

Dear Leslie J Blake,

An inspection of the above noted operation was conducted on April 04, 2017 by Resource Management Officer II Herbert Allen.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

ORIGINAL SIGNED

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Acting Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	L.J.'s Septic Services & Contracting Ltd.	Permit Expiry Date:	March 14, 2021
Land Use Permit No.	G16Q001	Previous Inspection:	November 03, 2016
Quarrying Permit No.		Inspection Date:	April 04, 2017
Contractor:	L.J.'s Septic Services & Contracting Ltd.	Subcontractor:	
Location(s) Inspected:	Frog Creek Km 126		
Current Stage of Operation:	Just started		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Frog Creek Quarry				
Permits	A				
Matters not Inconsistent	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

Frog Creek Quarry:

During the inspection at Frog Creek granular source on April 4, 2017 there were no concerns observed by the inspector.

At the site there were 2 D-10 cats and 1 excavator parked and 1 excavator was loading trucks with material from the southwestern corner of the pit.

An issuance letter dated March 2, 2017 from GTC indicated 30,000 cubic meters will be hauled to km 66 for storage. This material ties into the LUP # G17Q005

Representative Signature

Inspector's Signature

Date:	April 04, 2017	Permit #:	G16Q001	Page No:	1
-------	----------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

2 D-10 cats and on excavator at the frog creek site



Figure 2

Material being loaded into end dumps





ENVIRONMENTAL INSPECTION REPORT

Date:	April 04, 2017	Permit #:	G16Q001	Page No:	3
-------	----------------	-----------	---------	----------	---