



Telephone: 867-777-8907

Fax: 867-777-2090

May 1, 2017

L.J.'s Septic Services & Contracting Ltd.

P.O. Box 151

Fort McPherson, NT X0E 0J0

Attention: Leslie J Blake

|                   |                        |
|-------------------|------------------------|
| File Number       | G16Q001                |
| Type of Operation | QUARRY SITE - Existing |
| Location          | Frog Creek             |

Dear Leslie J Blake,

An inspection of the above noted operation was conducted on April 26, 2017 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.  
If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC: Dan Carmichael, Acting Superintendent, Department of Lands, Beaufort Delta Region

GLWB



## ENVIRONMENTAL INSPECTION REPORT

|  |   |                             |                |
|--|---|-----------------------------|----------------|
| <b>Permittee:</b>                      | L.J.'s Septic Services & Contracting Ltd. | <b>Permit Expiry Date:</b>  | March 14, 2021 |
| <b>Land Use Permit No.</b>             | G16Q001                                   | <b>Previous Inspection:</b> | April 04, 2017 |
| <b>Quarrying Permit No.</b>            |   | <b>Inspection Date:</b>     | April 26, 2017 |
| <b>Contractor:</b>                     | L.J.'s Septic Services & Contracting Ltd. | <b>Subcontractor:</b>       |                |
| <b>Location(s) Inspected:</b>          | Frog Creek                                |                             |                |
| <b>Current Stage of Operation:</b>     | Ongoing                                   |                             |                |
| <b>Program Modifications Approved:</b> |   |                             |                |

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

| Operating Condition                    | Aspect Inspected         |  |  |  |  |
|--|--------------------------|--|--|--|--|
|  | <b>Frog Creek Quarry</b> |  |  |  |  |
| Permits                                | A                        |  |  |  |  |
| Matters not Inconsistent               | A                        |  |  |  |  |
| Equipment as Approved (Type & Size)    | A                        |  |  |  |  |
| Methods & Techniques                   | A                        |  |  |  |  |
| Sections 8 to 12 / 14 to 16 M.V.L.U.R. | A                        |  |  |  |  |

**Explanatory Remarks -**

**Frog Creek Quarry:**

During the inspection on April 26, 2017 gravel was still being excavated and hauled from Frog Creek to Km 66 along the Dempster Highway.

There was 1 excavator loading trucks at the Frog Creek site, there was no stripping in the pit at the time of the inspection.

There is 1 semi truck, 1 excavator and 1 cat parked near where the excavation work was being conducted and 1 cat parked near the entrance to the pit.

As stated in the; *GTC issuance letter dated March 2, 2017 that conditions of authorization GTC17Q003 requires:*

**- Completion of Pre and post surveys.**

Please ensure these surveys be completed in a timely manner and forwarded to GTC.

Representative Signature

Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**Excavator on the stock pile**



**Figure 2**

**Semi truck parked at the Frog Creek site**





## ENVIRONMENTAL INSPECTION REPORT

**Figure 3**  
Excavator and cat parked at the Frog Creek site



**Figure 4**  
Cat parked near the entrance to the Frog Creek pit

