




Telephone: 867-777-8907  
Fax: 867-777-2090

November 7, 2016



L.J.'s Septic Services & Contracting Ltd.  
P.O. Box 151  
Fort McPherson, NT X0E 0J0

Attention: Leslie J Blake

File Number: G16Q001  
Type of Operation: QUARRY SITE - Existing  
Location: Frog Creek

Dear Leslie J Blake,

An inspection of the above noted operation was conducted on November 03, 2016 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.  
If you have any questions, please contact me at 867-777-8907.

Sincerely,



Herbert Allen  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC:  
Conrad Baetz, Regional Superintendent, Beaufort Delta Region  
GLWB  
GTC



## ENVIRONMENTAL INSPECTION REPORT

**FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF October 20, 2016**

Weekly submission reports are being submitted

<b>Permittee:</b>	L.J.'s Septic Services & Contracting Ltd.	<b>Permit Expiry Date:</b>	March 14, 2021
<b>Land Use Permit No.</b>	G16Q001	<b>Previous Inspection:</b>	October 20, 2016
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	November 03, 2016
<b>Contractor:</b>	L.J.'s	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Frog Creek		
<b>Current Stage of Operation:</b>	Done till next job		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected				
	Frog Creek Quarry				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

**Explanatory Remarks -**


**Frog Creek Quarry:**

During the inspection on November 3, 2016 there were no concerns observed by the inspector at the Frog Creek gravel pit.

On September 26, 2016 L.J.'s was given an issuance letter from GTC for the loading and hauling of 10,000 m<sup>3</sup> from Frog Creek to Fort McPherson.

A new section southwest of the pit, section #3 was opened up as indicated in the issuance letter and everything looks in order as to the letter. At the time of the inspection there was no activity at the pit.

Please ensure that the haul reports be submitted to GTC if the hauling is completed as stated in the issuance letter.



# ENVIRONMENTAL INSPECTION REPORT

Representative Signature

Inspector's Signature

Date:	November 03, 2016	Permit #:	G16Q001	Page No:	2
-------	-------------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**Stock pile at the center of the pit**



**Figure 2**

**Newly cleared section southwest section of the pit**





## ENVIRONMENTAL INSPECTION REPORT

**Figure 3**  
**Over burden pile**



**Figure 4**  
**New stock pile southwest section of the pit**

