




Telephone: 867 777-8900

Fax: 867-777-2090

October 21, 2016

L.J.'s Septic Services & Contracting Ltd.
P.O. Box 151
Fort McPherson, NT X0E 0J0

RECEIVED
OCT 31 2016


Attention: Leslie J Blake

File Number G16Q001
Type of Operation QUARRY SITE - Existing
Location Frog Creek

To: Leslie J Blake,

An inspection of the above noted operation was conducted on October 20, 2016 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,



Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Conrad Baetz, Regional Superintendent, Beaufort Delta Region
GLWB
GTC



ENVIRONMENTAL INSPECTION REPORT

Permittee:	L.J.'s Septic Services & Contracting Ltd.	Permit Expiry Date:	March 14, 2021
Land Use Permit No.	G16Q001	Previous Inspection:	October 06, 2016
Quarrying Permit No.		Inspection Date:	October 20, 2016
Contractor:		Subcontractor:	
Location(s) Inspected:	Frog Creek		
Current Stage of Operation:	ongoing		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Frog Creek Quarry				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -
Frog Creek Quarry:
 During the inspection it was observed that in permitted work area # 1 a estimate of 3 - 4000 m3 is stock piled. At work area # 2 a cat operator was pushing material and an estimated 4 - 5000m3 of material is pushed so far. No environmental concerns was observed during the inspection. Please ensure that as per condition # 3 of your issuance letter Dated Sept. 16 2016 that the weekly haul reports are being submitted to the GTC.

MATTERS FOR FOLLOW UP

Weekly submission reports are being submitted

N/A
 Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

entrance to Frog Creek



Figure 2

work area #1





ENVIRONMENTAL INSPECTION REPORT

Figure 3
work area #2



Figure 4
work area #2

