



Telephone: 867 777-8900
Fax: 867-777-2090

March 5, 2018

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: Lyle Gully

File Number G16Q004
Type of Operation QUARRY SITE - Existing
Location Km 251

To: Lyle Gully,

An inspection of the above noted operation was conducted on March 05, 2018 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF February 20, 2018
material is to be continually removed.

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	February 20, 2018
Quarrying Permit No.		Inspection Date:	March 05, 2018
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	Quarrying completed		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 251			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Chemicals	A			
Ecological Resources	A			
Fuel Storage	A			
Restoration of Lands	A			
Permits	U			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

Explanatory Remarks -

Km 251:

This inspection report is to inform that in 2016 a quarry permit was issued for 15000 cm and blasting and crushing for this material was completed. However no Pre and Post data was never provided on Quarry Permit 2016QP0016. This data was previously requested and has yet to be provided. Please note that as per conditions of your permit under Part A Scope of Permit item number 3 states;

"Compliance with the terms and conditions of this Permit does not excuse the Permittee from its obligation to comply with the requirements of any applicable Federal, Territorial, or municipal legislation."

Also under your Quarry Permit condition item 15 which states:

"This permit is subject to the provisions of the Territorial Quarry Regulations and the conditions set out herein. Failure to comply with the provisions of the Regulations and the



ENVIRONMENTAL INSPECTION REPORT

conditions prescribed in this permit may result in cancellation of the permit in accordance with Section 9(6) of the Territorial Quarrying Regulations without prior notice to the Permittee."

Please ensure that this matter is dealt with A.S.A.P.

Further please ensure that material is removed from site as this is a multi user site and the permit does not allow stock piling at site.

MATTERS FOR FOLLOW UP

Ensure pre and post data is received for quarry permit 2016QP0016 and material is being removed from site.

N/A

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2



Date:	March 05, 2018	Permit #:	G16Q004	Page No:	3
-------	----------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4



Date:	March 05, 2018	Permit #:	G16Q004	Page No:	4
-------	----------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6



Date:	March 05, 2018	Permit #:	G16Q004	Page No:	5
-------	----------------	-----------	---------	----------	---