



Telephone: 867-777-8907
Fax: 867-777-2090

July 15, 2021

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: Mosiul Alam

File Number	G17Q007
Type of Operation	QUARRY SITE - Existing
Location	Km 66

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on July 13, 2021 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:
Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB

Bag Service 1, Inuvik, NT X0E 0T0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	January 08, 2023
Land Use Permit No.	G17Q007	Previous Inspection:	June 23, 2021
Quarrying Permit No.		Inspection Date:	July 13, 2021
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 66		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 66				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Wildlife and Fisheries Habitat (Protection)	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Chemicals	A				

Explanatory Remarks -

Km 66:

During the inspection at Km 66 on July 13, 2021 there were no concerns by the inspectors.

There gravel is being removed from the site for the road maintenance at this time and the site is clean and in good order.

NA

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

