



Telephone: 867-777-8907
Fax: 867-777-2090

April 27, 2022

NWT Energy Corporation (03) Ltd.
4 Capital Drive
Hay River, NT XOE 1G2

Attention: Bruno Pereira

File Number G18X005
Type of Operation MISC.
Location Wind tower access

Dear Bruno Pereira,

An inspection of the above noted operation was conducted on April 26, 2022 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:
Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

DOI

GLWB

Bag Service 1, Inuvik, NT XOE 0T0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	NWT Energy Corporation (03) Ltd.	Permit Expiry Date:	November 26, 2025
Land Use Permit No.	G18X005	Previous Inspection:	April 12, 2022
Quarrying Permit No.	2021QP0032 - for 300,000cm	Inspection Date:	April 26, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	Wind tower access		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	KM 251	Wind tower access		
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wastes	A			
Ecological Resources	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			
Location as Permitted		A		
Time as Permitted		A		
Equipment as Approved (Type & Size)		A		
Methods & Techniques		A		
Facilities		A		
Erosion (Control or Prevention)		A		
Wildlife and Fisheries Habitat (Protection)		A		
Wastes		U		
Historical / Archaeological Sites		A		
Fuel Storage		A		
Restoration of Lands		A		
Permits		A		
Matters not Inconsistent		A		
Sections 12 to 19 T.L.U.R.		A		
Sections 8 to 12 / 14 to 16 M.V.L.U.R.		A		



ENVIRONMENTAL INSPECTION REPORT

Explanatory Remarks –
KM 251:

During the inspection on April 26, 2022 at Km 251 quarry there is no concern that was observed by the inspector at the site but there is blasting occurring before pre data and post are up dated.

We did receive one pre data since the start on the project but have yet to receive other pre and post data required in the conditions of the quarry permit. There were blasts that occurred which we received the emails for after the first blast at the start of the project.

Quarry permit conditions:

7. All surveyed data submitted (Including pre and post blasts if applicable) shall be in an electronic format with waypoints, shape files and excel spreadsheets compatible the ArcGIS 9.3 or as approved by the inspector.

9. Pre-surveys must be submitted to the land use inspector 10 days prior to commencement of the operation.

Wind tower access:

During the inspection at wind tower access road, there was one concern observed by the inspector.

There is some plastic wrapping and paper tubing piling up near the entrance that needs to be removed before the wind takes it away.

Please keep in mind that the climate is warming and rutting can occur which can be an issue with this project.

Representative Signature

Inspector's Signature

Date:	April 26, 2022	Permit #:	G18X005	Page No:	2
-------	----------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6



Date:	April 26, 2022	Permit #:	G18X005	Page No:	5
-------	----------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 7



Figure 8

