



Telephone: 867-678-8090 ext. 24653
Fax: 867-777-2090

October 21, 2022

NWT Energy Corporation (03) Ltd.
4 Capital Drive
Hay River, NT XOE 1G2

Attention: Bruno Pereira

File Number G18X005
Type of Operation MISC.
Location Wind tower site and access road

Dear Bruno Pereira,

An inspection of the above noted operation was conducted on October 20, 2022 by Manager, Resource Management Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-678-8090 ext. 24653.


Sincerely,

Herbert Allen
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC:
Donald Arey, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB

Bag Service 1, Inuvik, NT XOE OT0





ENVIRONMENTAL INSPECTION REPORT

Permittee:	NWT Energy Corporation (03) Ltd.	Permit Expiry Date:	November 26, 2025
Land Use Permit No.	G18X005	Previous Inspection:	September 20, 2022
Quarrying Permit No.	2021QP0032 - for 300,000cm	Inspection Date:	October 20, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	Wind tower site and access road		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Wind Tower access and pad				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Sections 12 to 19 T.L.U.R.	A				

Explanatory Remarks -

Wind Tower access and pad:

During the inspection on October 20, 2022 at the high point wind tower site and access road there were no concerns observed by the inspectors.

There is a huge crane set up and ready to go at the wind tower site on top of the newly build pad. The area at the wind tower site is clean and in good order and there is no concerns by the inspector.

The work on widening and building up the road is still in progress and moving along. There has been a big snow fall since the last inspection and is hard to view any concerns.

Representative Signature

Inspector's Signature

Date:	October 20, 2022	Permit #:	G18X005	Page No:	1
-------	------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6





ENVIRONMENTAL INSPECTION REPORT

Figure 7



Figure 8

