



Telephone: 867-777-8907

Fax: 867-777-2090

July 4, 2022

NWT Energy Corporation (03) Ltd.
4 Capital Drive
Hay River, NT XOE 1G2

Attention: Bruno Pereira

File Number	G18X005
Type of Operation	MISC.
Location	Wind tower access and tower pad

Dear Bruno Pereira,

An inspection of the above noted operation was conducted on June 30, 2022 by Acting Manager of Resource Management Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Acting Manager of Resource Management
Department of Lands
Beaufort Delta Region

CC:

Donald Arey, Acting Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	NWT Energy Corporation (03) Ltd.	Permit Expiry Date:	November 26, 2025
Land Use Permit No.	G18X005	Previous Inspection:	June 02, 2022
Quarrying Permit No.	2021QP0032 - for 300,000cm	Inspection Date:	June 30, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	Wind tower access and tower pad		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Wind Tower access and pad				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Sections 12 to 19 T.L.U.R.	A				

Explanatory Remarks -
Wind Tower access and pad:

During the inspection on June 30, 2022 at the wind tower access road and the tower pad there were no concerns observed by the inspector.

The work on the tower pad is still in progress and looks like its almost ready for the next stage. The site is in good order and there are no concerns.

The work on widening and building up the road is still in progress and moving forward. There is water seeping through the gravel on the road in one area and there are a few soft spots on the road that may cause problems for equipment and should be fixed.

Representative Signature

Inspector's Signature

Date:	June 30, 2022	Permit #:	G18X005	Page No:	1
-------	---------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

