



Telephone: 867-777-8907
Fax: 867-777-2090

July 15, 2021

NWTEL Inc.
183 Range Road
Whitehorse, YT Y1A 3E5

Attention: **Tricia McIntyre**

File Number G19H010
Type of Operation FUEL CACHES
Location NWT/Yukon border

Dear Tricia McIntyre,

An inspection of the above noted operation was conducted on July 13, 2021 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:
Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB

Bag Service 1, Inuvik, NT X0E 0T0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	NWTEL Inc.	Permit Expiry Date:	January 26, 2026
Land Use Permit No.	G19H010	Previous Inspection:	July 14, 2020
Quarrying Permit No.		Inspection Date:	July 13, 2021
Contractor:		Subcontractor:	
Location(s) Inspected:	NWT/Yukon border		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	NWT/Yukon	NWTEL	Tower	
Location as Permitted	A			
Time as Permitted	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Fuel Storage	A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

Explanatory Remarks -
 NWT/Yukon NWTEL Tower:

During the inspection on July 13, 2021 at microwave tower along the NWT/Yukon border there are no concerns observed by the inspector.

The site is clean and in good order.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

