



Telephone: 867 777-8900

Fax: 867-777-2090

April 29, 2020

EGT Northwind
P.O. Box 1700
Inuvik, NT X0E0T0

Attention: Kurt Wainman

File Number G19S011
Type of Operation SOIL TESTING (GEOTECH)
Location Km 230

To: Kurt Wainman,

An inspection of the above noted operation was conducted on April 23, 2020 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Original Signed

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
Gwich'in Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	EGT Northwind	Permit Expiry Date:	January 26, 2022
Land Use Permit No.	G19S011	Previous Inspection:	March 05, 2020
Quarrying Permit No.	Km 230	Inspection Date:	April 23, 2020
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 230		
Current Stage of Operation:	ongoing		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 230 geotech				
Time as Permitted	U				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Sections 12 to 19 T.L.U.R.	A				

Explanatory Remarks -

Km 230 goetek:

During the last inspection dated March 06, 2020, it was requested that a map and which boreholes was drilled. During this inspection it was observed that work is currently being done at the site. The unsatisfactory given here is result that the map and bore holes drilled location were not recieved by our office as requested.

MATTERS FOR FOLLOW UP

drilled location coordinates and map

Representative Signature

Inspector's Signature

Date:	April 23, 2020	Permit #:	G19S011	Page No:	1
-------	----------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3

