



Telephone: 867-777-8907

Fax: 867-777-2090

February 27, 2020

Hamlet of Aklavik
P.O. Box 88
Aklavik, NT X0E0A0

Attention: Fred Bahrens

File Number	G20Q001
Type of Operation	ROADS, winter (during Const)
Location	Willow River

Dear Fred Bahrens,

An inspection of the above noted operation was conducted on February 27, 2020 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

ORIGINAL SIGNED

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:
Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB
GTC



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Hamlet of Aklavik	Permit Expiry Date:	February 17, 2025
Land Use Permit No.	G20Q001	Previous Inspection:	New
Quarrying Permit No.	467	Inspection Date:	February 27, 2020
Contractor:	Hamlet of Aklavik	Subcontractor:	
Location(s) Inspected:	Willow River		
Current Stage of Operation:	Just starting		
Program Modifications Approved:			

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable “N/I” - Not Inspected

Operating Condition	Aspect Inspected				
	Willow River				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Wildlife and Fisheries Habitat (Protection)	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

Willow River:

During the inspection on February 27, 2020 at the Willow River winter access road there were no concerns observed by the inspector.

The work is just getting started and they are working on plowing the road through with the snow cat and the ramp from Husky River to the start of the winter access road is completed and in good condition.

We got as far as the first lake as rest of the road was not watered down to build up the ice. There is just the snow cats working at the road at this time.

Representative Signature

Inspector’s Signature

Date:	February 27, 2020	Permit #:	G20Q001	Page No:	1
-------	-------------------	-----------	---------	----------	---




ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

