



Telephone: 867 777-8900

Fax: 867-777-2090

March 20, 2020

Hamlet of Aklavik
P.O. Box 88
Aklavik, NT X0E0A0

Attention: Fred Bahrens

File Number G20Q001
Type of Operation ROADS, winter (during Const)
Location Aklavik Source 467 - willow river

To: Fred Bahrens,

An inspection of the above noted operation was conducted on March 19, 2020 by Manager, Resource Management Donald Arey and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to general comments section of this report.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Beaufort Delta
GTC
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Hamlet of Aklavik	Permit Expiry Date:	February 17, 2025
Land Use Permit No.	G20Q001	Previous Inspection:	March 11, 2020
Quarrying Permit No.	GTC19Q001	Inspection Date:	March 19, 2020
Contractor:		Subcontractor:	
Location(s) Inspected:	Aklavik Source 467 - willow river		
Current Stage of Operation:	startup on material		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Willow River				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Wildlife and Fisheries Habitat (Protection)	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

Willow River:

Inspectors met with Permittee at source 467-Willow River, and had gone over the work location. Equipment currently on site is a D4, D6 and D8 cat, with one excavator. Material is now being pushed by the D8 cat. All matters was satisfactory with inspector with no environmental concerns.

N/A

Representative Signature

[Signature]

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

