



Telephone: 867-777-8907

Fax: 867-777-2090

August 25, 2022

Department of Infrastructure
Bag service # 1
106 Veteran Way
Inuvik, NT X0E0T0

Attention: Mosiul Alam

File Number G21E001
Type of Operation HWY MAINTENANCE & OPERATIONS
Location Km 230

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on August 23, 2022 by Manager of Resource Management Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Manager of Resource Management
Department of Lands
Beaufort Delta Region

CC:
Donald Arey, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB

Bag Service 1, Inuvik, NT X0E 0T0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Department of Infrastructure	Permit Expiry Date:	June 27, 2026
Land Use Permit No.	G21E001	Previous Inspection:	August 23, 2022
Quarrying Permit No.		Inspection Date:	August 23, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 230		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Operation			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Historical / Archaeological Sites	A			
Ecological Resources	A			
Fuel Storage	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			
Location as Permitted	A			

Explanatory Remarks - Operation :

During the inspection on August 23, 2022 at Km 230 there were no concerns observed by the inspector.

There were a couple of people working on a excavator at the mid section of the pit and all the other equipment were idle at the site. There are 3 stock piles of material at the site.

The site is clean and in good order.

Please submit a pre and post data for the material used for the highway maintenance to date.

Representative Signature

Inspector's Signature

Date:	August 23, 2022	Permit #:	G21E001	Page No:	1
-------	-----------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

