



Telephone: 867-678-8090 ext. 24656

Fax: 867-777-2090

October 18, 2022

Department of Infrastructure
Bag service # 1
106 Veteran Way
Inuvik, NT X0E0T0

Attention: Mosiul Alam

File Number G21E001
Type of Operation HWY MAINTENANCE & OPERATIONS
Location KM 230

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on October 17, 2022 by Resource Management Officer, Jozef Carnogursky.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 ext. 24656 .

Sincerely,

Jozef Carnogursky
Resource Management Officer II

CC: Gwich'in Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Department of Infrastructure	Permit Expiry Date:	June 27, 2026
Land Use Permit No.	G21E001	Previous Inspection:	October 17, 2022
Quarrying Permit No.		Inspection Date:	October 17, 2022
Contractor:		Subcontractor:	230
Location(s) Inspected:	KM 230		
Current Stage of Operation:	Complete		
Program Modifications Approved:	NA		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Operation				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	U				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	U				
Historical / Archaeological Sites	A				
Ecological Resources	A				
Fuel Storage	U				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				

Explanatory Remarks -

Operation :

A loader tire some wooden debris and a pail of a petroleum product was left on site contrary to permit conditions.

A follow up inspection will occur in 7 days to ensure Permit conditions are complied with.



ENVIRONMENTAL INSPECTION REPORT

Representative Signature

[Handwritten Signature]

Inspector's Signature

Date:	October 17, 2022	Permit #:	G21E001	Page No:	2
-------	------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Loader tire left on site



Figure 2

Wooden debris left on site





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Pale left on site

