



Telephone: 867-777-8907
Fax: 867-777-2090

July 15, 2021

Department of Infrastructure
Bag service # 1
106 Veteran Way
Inuvik, NT X0E0T0

Attention: Mosiul Alam

File Number G21E001
Type of Operation HWY MAINTENANCE & OPERATIONS
Location Km 235

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on July 13, 2021 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:
Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB

ENVIRONMENTAL INSPECTION REPORT

Permittee:	Department of Infrastructure	Permit Expiry Date:	June 27, 2026
Land Use Permit No.	G21E001	Previous Inspection:	New
Quarrying Permit No.		Inspection Date:	July 13, 2021
Contractor:	Bob's Welding LTD	Subcontractor:	
Location(s) Inspected:	Km 235		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N / I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 235				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Wildlife and Fisheries Habitat (Protection)	A				
Historical / Archaeological Sites	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 12 to 19 T.L.U.R.	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

Km 235:

During the inspection on July 13, 2021 at Km 235 gravel source there were no concerns at the time of the inspection.

Bob's Welding's crew were crushing and stock piling material for the highway project at the east side of the gravel pit.

The site looks in good order.

Please note as well stock piles are to be continually removed from site, as per your L.U.P. Part A scope of Permit, item 1 a . temporary stockpiling and hauling of granular material from the quarry at km 235, also the central area of the pit is to be free of any stock piles and equipment.



Representative Signature



Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

