



Telephone: 867-678-8090 ext. 24656

Fax: 867-777-2090

October 19, 2022

Arctic Tire (1980) Ltd  
P.O. Box 3190  
Inuvik, NT X0E 0T0

**Attention: Brian McCarthy**

<b>File Number</b>	<b>G21Q002</b>
<b>Type of Operation</b>	<b>QUARRY SITE - Existing</b>
<b>Location</b>	<b>KM 251</b>

Dear Brian McCarthy,

An inspection of the above noted operation was conducted on October 17, 2022 by Resource Management Officer, Jozef Carnogursky.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report.

If you have any questions, please contact me at 867-678-8090 ext. 24656 .

Sincerely,

Jozef Carnogursky  
Resource Management Officer

CC: Gwich'in Land and Water Board

## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Arctic Tire (1980) Ltd	<b>Permit Expiry Date:</b>	June 27, 2026
<b>Land Use Permit No.</b>	G21Q002	<b>Previous Inspection:</b>	New
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	October 17, 2022
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	KM 251		
<b>Current Stage of Operation:</b>	Inactive		
<b>Program Modifications Approved:</b>	NA		

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected			
	KM 251			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Fuel Storage	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			

**Explanatory Remarks -**

**KM 251:**

All aspects were satisfactory at the time of inspection. No work has been occurring under this permit at the time of inspection.

\_\_\_\_\_  
Representative Signature

  
\_\_\_\_\_  
Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**



**Figure 2**

