



Telephone: 867-678-8090 ext. 24653

Fax: 867-777-2090

October 19, 2023

GNWT Department of Infrastructure  
Bag Service #1, 106 Veterans Way  
Inuvik, NT X0E 0T0

Attention: Allan Hamilton

File Number G20H006  
Type of Operation CAMPS  
Location James Creek km 14.2

Dear Allan Hamilton,

An inspection of the above noted operation was conducted on October 18, 2023 by Resource Management Officer Herbert Allen and Resource Management Officer Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely

Herbert Allen  
Resource Management Officer  
Department of Environment and Climate  
Change Land and Water  
Beaufort Delta Region

CC:



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	August 05, 2023
<b>Land Use Permit No.</b>	G20H006	<b>Previous Inspection:</b>	September 27, 2023
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	October 18, 2023
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	James Creek km 14.2		
<b>Current Stage of Operation:</b>	On-going		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected			
	<b>James Creek Km 14.2</b>			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Fuel Storage	A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			

**Explanatory Remarks -**

James Creek Km 14.2:

During the inspection at the James Creek maintenance camp on October 18, 2023 there were no concerns observed by the inspector.

The site was clean and organized and in good condition.

Representative Signature

Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:  
**Figure 1**



**Figure 2**





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

