



Telephone: 867-678-8090 ext. 24653

Fax: 867-777-2090

September 28, 2023

GNWT Department of Infrastructure
Bag Service #1, 106 Veterans Way
Inuvik, NT X0E 0T0

Attention: Mosiul Alam

File Number G20H006
Type of Operation CAMPS
Location James Creek Km 14.2

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on September 27, 2023 by Resource Management Officer Herbert Allen and Resource Management Officer Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen
Resource Management Officer
Department of Environment and Climate
Change Land and Water
Beaufort Delta Region

CC:

Donald Arey, Acting Regional Superintendent, Department of Environment and Climate Change Land and Water, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	August 05, 2023
Land Use Permit No.	G20H006	Previous Inspection:	September 18, 2023
Quarrying Permit No.		Inspection Date:	September 27, 2023
Contractor:	L.J.'s Septic Services & Contracting Ltd.	Subcontractor:	
Location(s) Inspected:	James Creek Km 14.2		
Current Stage of Operation:			
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	James Creek Km 14.2				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				
Time as Permitted	A				

Explanatory Remarks -

James Creek Km 14.2:

During the inspection on September 27, 2023 at the James Creek maintenance camp there were no concerns by the inspectors.

The site was clean and in good order.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

