



INSPECTION DATE – December 16th 2021

ENVIRONMENTAL INSPECTION REPORT (MV2019X0007)

Permittee:	CIRNAC – CARD (Giant)	August 6 th 2025	November 8 th 2021
------------	-----------------------	-----------------------------	-------------------------------

		Permit Expiry Date	Last Previous Inspection
Land Use Permit No.	MV2019X0007		
Quarrying Permit No.	N/A		
Contractor:	Parsons	Subcontractor:	Forward Mining

Location(s) Inspected:	Waste Storage Locations, Old Town Site, Blasting Area
------------------------	---

Current Stage of Operation:	Active Remediation
-----------------------------	--------------------

Program Modifications Approved:	N/A
---------------------------------	-----

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

	Operating Condition	Aspect Inspected			
		Drilling Location			
	Scope of Permit	A			
A	Location and Area	A			
B	Time	A			
C	Equipment (Type and Size)	A			
D	Methods and Techniques	A			
E	Facilities	A			
F	Erosion (Control or Prevention)	A			
G	Chemicals	A			
H	Wildlife and Fisheries Habitat (Protection)	A			
I	Wastes	A			
J	Historical / Archaeological Sites	A			
M	Fuel Storage	A			
N	Brush Disposal	A			
O	Restoration of Lands	A			
P	Permits	A			
Q	Protection of Land	A			
	Matters Not Inconsistent	A			
	Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			
	Quarrying Methods	N/A			



ENVIRONMENTAL INSPECTION REPORT Pg. 2 (Continued)

Date:	December 16 th 2021	Permit #:	MV2019X0007
-------	--------------------------------	-----------	-------------

Explanatory Remarks:

An inspection of the CIRNAC Giant Mine land use permit occurred on December 16th 2021. The inspection was conducted to ensure compliance with the conditions annexed in the land use permit, approved management plans, and the *Mackenzie Valley Land Use Regulations*.

Many of the activities onsite have been temporarily shutdown due to the holiday season. The blasting onsite was not active at the time of the inspection (Photo #1). All of the equipment used to blast and remove the material was stored onsite near the blasting area in accordance with the terms and conditions of the land use permit (Photo #2). This includes the placement of drip trays and regular inspections to ensure that no leaks of hydrocarbons are present.

The non-hazardous landfill is near completion (Photo #3), Forward Mining will return in the new year to complete the minimal amount of work remaining. The Inspector is unable to complete a detailed inspection of the landfill as it is covered in snow. The Inspector will ensure that the facility has been constructed in accordance with the design specifications in spring.

The brushing program near the old town site has been completed and was done to avoid complications due to wildlife and song birds nesting in the area. The Permittee took great care not to over clear the area and has placed the brush in piles for easy removal (Photo #4).

The Permittee has shown continuous forward thinking and anticipation with future issues such as the nesting birds near the town site. As always the Permittee continuously communicates with the Inspector and it appears that the site is very well managed and organized.

Inspectors Signature



Photo #1: Overview of the blasting area located northwest of the C-Dry building



Photo #2: Blasting and rock removal equipment stored until the program resumes



Photo #3: Overview of the non-hazardous landfill



Photo #4: Overview of the brush piles located near the old town site