



Department of Lands  
Dehcho Region  
P.O. Box 150  
Fort Simpson, NT X0E 0N0

Telephone: 867-695-2626 ext. 205  
Fax: 867-695-2615

February 26, 2020

Enbridge Pipelines (NW) Inc  
PO Box 280  
Norman Wells, NT X0E 0V0

**Attention: Erin Sanford**

<b>File Number</b>	<b>MV2013P0011</b>
<b>Type of Operation</b>	<b>PIPELINES (existing)</b>
<b>Location</b>	Shoofly access to KP 309

Dear Erin Sanford,

An inspection of the above noted operation was conducted on February 20, 2020 by Resource Management Officer II Danielle Rogers and Manager, Resource Management Kyle Christiansen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-695-2626 ext. 205.

Sincerely,

Danielle Rogers  
Resource Management Officer II  
Department of Lands  
Dehcho Region

CC: Angela Love- Regulatory Specialist, MVLWB  
Laurie Nadia- Regional Superintendent, Department of Lands, Dehcho Region  
Kyle Christiansen- Manager, Resource Management, Department of Lands, Dehcho Region



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Enbridge Pipelines (NW) Inc	<b>Permit Expiry Date:</b>	July 17, 2020
<b>Land Use Permit No.</b>	MV2013P0011	<b>Previous Inspection:</b>	February 20, 2020
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	February 20, 2020
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Shoofly access to KP 309		
<b>Current Stage of Operation:</b>	Ongoing		
<b>Program Modifications Approved:</b>	N/A		

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected				
	Shoofly				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				

**Explanatory Remarks -**

Inspectors from the Department of Lands conducted an inspection of MV2013P0011 on February 20, 2020. The shoofly had adequate snow/ice buildup. There was no rutting at the time of the inspection. There was one spot where the ice was melted resulting in exposed ground. There was no machinery or fuels on site at the time of the inspection. Inspectors have no concerns and will continue to monitor the shoofly access.



## ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**Shoofly entrance**



**Figure 2**

**Access with melted spot**





## ENVIRONMENTAL INSPECTION REPORT

**Figure 3**

**Melted spot with exposed ground**



**Figure 4**

**Shoofly access**

