



Telephone: 867 874-6994

Fax: 867 874-2460

August 5, 2016

ProCore Drilling Ltd.
28067B Mackenzie Highway
email: ddean@northwestel.net
Hay River, NT X0E 0R4

Attention: Darrel Dean

File Number	MV2013Q0017
Type of Operation	QUARRY SITE - New
Location	Sites A and C, Km 34.1, NWT Highway No. 5

Dear Mr. Dean,

An inspection of the above noted operation was conducted on June 27, 2016 by Resource Management Officers Jayda Robillard and Norm McCowan.

Enclosed is a copy of the Environmental Inspection Report. All aspects of your operation appears satisfactory at the time of inspection.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

ORIGINAL SIGNED

Jayda Robillard
Resource Management Officer II
Department of Lands
South Slave Region

CC: MVLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	ProCore Drilling Ltd.	Permit Expiry Date:	May 21, 2019
Land Use Permit No.	MV2013Q0017	Previous Inspection:	October 26, 2015
Quarrying Permit No.	2014QP0054	Inspection Date:	June 27, 2016
Contractor:		Subcontractor:	
Location(s) Inspected:	Sites A and C, Km 34.1, NWT Highway No. 5		
Current Stage of Operation:	No sign of recent activity.		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Site A	Site C			
Equipment as Approved (Type & Size)	A	A			
Facilities	A	A			
Erosion (Control or Prevention)	A	A			
Chemicals	A	A			
Wildlife and Fisheries Habitat (Protection)	A	A			
Wastes	A	A			
Historical / Archaeological Sites	N/A	N/A			
Fuel Storage	A	A			
Brush Disposal	N/A	N/A			
Restoration of Lands	N/A	N/A			
Location as Permitted	A	A			
Time as Permitted	A	A			
Permits	A	A			

Explanatory Remarks -

Site A:

No sign of recent activity.

Site C:

No sign of recent activity.

Please note you have 170m³ of material remaining on your quarry permit. You will require a new quarry permit once this amount has been removed from site or when the quarry permit expires on October 5, 2017.

All aspects of your operation appeared satisfactory at the time of inspection.

ORIGINAL SIGNED

Representative Signature

Inspector's Signature

Date:	June 27, 2016	Permit #:	MV2013Q0017	Page No:	1
-------	---------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Site C stockpile



Figure 2

Site C, photo taken facing east.





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Stockpile at the entrance to Site A



Figure 4

Site A stockpile

