



Telephone: 867 874-6994

Fax: 867 874-2460

June 13, 2017

ProCore Drilling Ltd.
28067B Mackenzie Highway
email: ddean@northwestel.net
Hay River, NT X0E 0R4

Attention: Darrel Dean

File Number	MV2013Q0017
Type of Operation	QUARRY SITE - New
Location	NWT Highway No. 5, Km 34.1 - Sites A and C

Dear Mr. Dean,

An inspection of the above noted operation was conducted on May 09, 2017 by Resource Management Officers Jayda Robillard and Norm McCowan.

Enclosed is a copy of the Environmental Inspection Report. All aspects of your operation appeared satisfactory and no environmental concerns were noted at the time of inspection.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

ORIGINAL SIGNED

Jayda Robillard
Resource Management Officer II
Department of Lands
South Slave Region

CC: Mackenzie Valley Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	ProCore Drilling Ltd.	Permit Expiry Date:	May 21, 2019
Land Use Permit No.	MV2013Q0017	Previous Inspection:	October 06, 2016
Quarrying Permit No.	2014QP0054	Inspection Date:	May 09, 2017
Contractor:		Subcontractor:	
Location(s) Inspected:	NWT Highway No. 5, Km 34.1 - Sites A and C		
Current Stage of Operation:	No sign of recent quarrying activity.		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Site A	Site C		
Erosion (Control or Prevention)	A	A		
Chemicals	A	A		
Wildlife and Fisheries Habitat (Protection)	A	A		
Wastes	A	A		
Historical / Archaeological Sites	A	A		
Fuel Storage	A	A		
Brush Disposal	A	A		
Restoration of Lands	A	A		
Location as Permitted	A	A		
Time as Permitted	A	A		
Permits	A	A		
Equipment as Approved (Type & Size)	A	A		
Facilities	A	A		

Explanatory Remarks -

Site A:

There was no recent quarrying activity at Site A. There are 2 stockpiles of granular material on site.

Site C:

There was no recent quarrying activity at Site C. There are three stockpiles of processed granular material on site.

Please note you have 140m³ remaining on your quarry permit. You will require a new quarry permit once this amount has been removed from site or when the quarry permit expires on October 5, 2017.

All aspects of your operation appeared satisfactory at the time of inspection.



ENVIRONMENTAL INSPECTION REPORT

ORIGINAL SIGNED

Representative Signature

Inspector's Signature

Date:	May 09, 2017	Permit #:	MV2013Q0017	Page No:	2
-------	--------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Site A: Stockpile



Figure 2

Site A: Stockpile near the entrance to Site A.





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Site C: Facing west stockpile area at Site C.



Figure 4

Site C: Facing west, the active face at the back of the photo.

