



Telephone: 867 874-6994

Fax: 867 874-2460

November 28, 2017

ProCore Drilling Ltd.  
28067B Mackenzie Highway  
email: ddean@northwestel.net  
Hay River, NT X0E 0R4

**Attention: Darrel Dean**

<b>File Number</b>	<b>MV2013Q0017</b>
<b>Type of Operation</b>	<b>QUARRY SITE - New</b>
<b>Location</b>	<b>Km 34.1, NWT Highway No. 5, Sites A &amp; C</b>

Dear Mr. Dean,

An inspection of the above noted operation was conducted on October 26, 2017 by Resource Management Officers Jayda Robillard and Norm McCowan.

Enclosed is a copy of the Environmental Inspection Report. No environmental concerns were noted during the inspection.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

**ORIGINAL SIGNED**

Jayda Robillard  
Resource Management Officer II  
Department of Lands  
South Slave Region

CC: Mackenzie Valley Land and Water Board  
Derise Rehm-Lepine, Regional Superintendent South Slave



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	ProCore Drilling Ltd.	<b>Permit Expiry Date:</b>	May 21, 2019
<b>Land Use Permit No.</b>	MV2013Q0017	<b>Previous Inspection:</b>	May 09, 2017
<b>Quarrying Permit No.</b>	2017QP0025	<b>Inspection Date:</b>	October 26, 2017
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 34.1, NWT Highway No. 5, Sites A & C		
<b>Current Stage of Operation:</b>	There was no equipment in the pit at the time of inspection.		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected			
	Site A	Site C		
Erosion (Control or Prevention)	A	A		
Chemicals	A	A		
Wildlife and Fisheries Habitat (Protection)	A	A		
Wastes	A	A		
Historical / Archaeological Sites	A	A		
Fuel Storage	A	A		
Brush Disposal	A	A		
Restoration of Lands	A	A		
Location as Permitted	A	A		
Time as Permitted	A	A		
Permits	A	A		
Equipment as Approved (Type & Size)	A	A		
Facilities	A	A		

**Explanatory Remarks:**

**Site C:**

A small amount of material has been removed from the large stockpile of processed granular material at Site C under the authority of quarry permit #2014QP0054. There has been no recent activity.

**Site A:**

A new quarry permit #2017QP0025 for 1000m<sup>3</sup> was issued on September 1, 2017. Please ensure you submit a monthly quarry report to our office prior to the 10th day of each month as per Condition 11 of your quarry permit.

No environmental concerns were noted during the inspection.

ORIGINAL SIGNED

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature

Date:	October 26, 2017	Permit #:	MV2013Q0017	Page No:	1
-------	------------------	-----------	-------------	----------	---



## ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**Site A stockpile**



**Figure 2**

**Site C material has been quarried this season.**







## ENVIRONMENTAL INSPECTION REPORT

**Figure 3**  
**Site C, facing west.**

