



Telephone: 867 874-6994  
Fax: 867 874-2460

December 2, 2016

ProCore Drilling Ltd.  
28067B Mackenzie Highway  
email: ddean@northwestel.net  
Hay River, NT X0E 0R4

**Attention: Darrel Dean**

**File Number** MV2013Q0017  
**Type of Operation** QUARRY SITE - New  
**Location** Sites A and C, Km 34.1, NWT Highway No. 5

Dear Mr. Dean,

An inspection of the above noted operation was conducted on October 06, 2016 by Resource Management Officers Jayda Robillard and Norm McCowan.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

**Please note: Condition 11** of your quarry permit requires that you submit monthly quarry reports. A monthly report has not been received from ProCore Drilling since December 2015 and at that time only 170m<sup>3</sup> remained on your quarry permit. **Please submit a monthly report accounting for all granular material removed since December 2015 by January 10th to our office or your quarry permit may be cancelled.** A copy of the monthly quarry report has been attached for your use. Note our office is closed from December 22, 2016 to January 2, 2017. We will reopen on January 3, 2017.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

**ORIGINAL SIGNED**

Jayda Robillard  
Resource Management Officer II  
Department of Lands  
South Slave Region

CC: Mackenzie Valley Land and Water Board



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	ProCore Drilling Ltd.	<b>Permit Expiry Date:</b>	May 21, 2019
<b>Land Use Permit No.</b>	MV2013Q0017	<b>Previous Inspection:</b>	June 27, 2016
<b>Quarrying Permit No.</b>	2014QP0054	<b>Inspection Date:</b>	October 06, 2016
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Sites A and C, Km 34.1, NWT Highway No. 5		
<b>Current Stage of Operation:</b>	There was no equipment in the pit at the time of inspection.		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected			
	Site A	Site C		
Erosion (Control or Prevention)	A	A		
Chemicals	A	A		
Wildlife and Fisheries Habitat (Protection)	A	A		
Wastes	A	A		
Historical / Archaeological Sites	N/A	N/A		
Fuel Storage	A	U(36)		
Brush Disposal	N/A	N/A		
Restoration of Lands	N/A	N/A		
Location as Permitted	A	A		
Time as Permitted	A	A		
Permits	A	A		
Equipment as Approved (Type & Size)	A	A		
Facilities	A	A		

Explanatory Remarks -

Site C:

Granular material has been removed from large stockpile at Site C and quarrying activity has taken place at the west end of the land use area recently.

**Condition 36:** There are several small spills near the working face of the large stockpile in Site C. These must be cleaned up and taken to an authorized disposal area.

**Condition 11** of your quarry permit requires that you submit monthly quarry reports. A monthly report has not been received from ProCore Drilling since December 2015 and at that time only 170m<sup>3</sup> remained on your quarry permit. **Please submit a monthly report accounting for all granular material removed since December 2015 by January 10th to our office or your quarry permit may be cancelled.** A copy of the monthly quarry report has been attached for your use.



## ENVIRONMENTAL INSPECTION REPORT

Site A:  
There has been no quarrying activity at Site A this season.

ORIGINAL SIGNED

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature

Date:	October 06, 2016	Permit #:	MV2013Q0017	Page No:	2
-------	------------------	-----------	-------------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**Stockpile at Site A.**



**Figure 2**

**Stockpile at the entrance to Site A.**



**Figure 3**

**Large stockpile at Site C.**



**Figure 4**

**Small spills near the large stockpile at Site C.**



**Figure 5**

**More small spills at the large stockpile at Site C.**



**Figure 6**

**Quarrying activity has taken place at the west end of Site C.**

