



South Slave Region
41 Capital Drive #203
Hay River, NT X0E 1G2

Telephone: 867 874-6994
Fax: 867 874-2460

November 20, 2014

ProCore Drilling Ltd.
28067B Mackenzie Highway
Hay River, NT X0E 0R4

Attn: Darrell Dean

**RE: Land Use Permit M2013Q0017
QUARRY SITE
NWT Highway No. 5, Km 34.1 Sites A & C**

Dear Mr. Dean,

An inspection of the above noted operation was conducted on October 21, 2014 by Resource Management Officers Jayda Robillard and Norm McCowan.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

ORIGINAL SIGNED

Jayda Robillard
Resource Management Officer II
Department of Lands
South Slave Region

Cc: MVLWB
Maurice Evans, Regional Superintendent South Slave – Department of Lands
Erin Anderson, Land Use Advisor – Department of Lands



ENVIRONMENTAL INSPECTION REPORT

Permittee:	ProCore Drilling Ltd.	Permit Expiry Date:	May 21, 2019
Land Use Permit No.	M2013Q0017	Previous Inspection:	August 12, 2014
Quarrying Permit No.	2014QP0054	Inspection Date:	October 21, 2014
Contractor:		Subcontractor:	
Location(s) Inspected:	NWT Highway No. 5, Km 34.1 Sites A & C		
Current Stage of Operation:	Granular material has been removed from Sites A & C under the authority of quarry permit #2014QP0054.		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Pit				
Brush Disposal	A				
Chemicals	A				
Equipment as Approved (Type & Size)	A				
Erosion (Control or Prevention)	A				
Facilities	U(11)				
Fuel Storage	A				
Historical / Archaeological Sites	A				
Location as Permitted	A				
Permits	A				
Restoration of Lands	A				
Time as Permitted	A				
Wastes	U (25)				
Wildlife and Fisheries Habitat (Protection)	A				

Explanatory Remarks -

Site A: A significant amount of material has been removed from the stockpile at Site A. Garbage consisting of floats from a fishnet and a blue plastic bin has been left at the site. This garbage does not belong to ProCore Drilling but should be removed to discourage the public from using this site as a dumping ground (Condition 11). Material has also been removed from the stockpile at the entrance to Site A.

Site C: Material has been removed from the stockpiles at Site C. The old dryer remains on site and must be removed from territorial lands and taken to an authorized disposal facility as per Condition 25 of your land use permit.

Please note, as per Condition 11 of your Quarry Permit "Prior to the tenth day of each month, the Permittee shall submit a report to the Land Use Inspector at fax number (867) 874-2460, indicating the quantity of material quarried and the quantity of material removed from the site. Failure to submit the monthly report within indicated time frames may result in cancellation of this permit as per section 12 (5) of the regulations." Please ensure these reports are being sent to our office each month, a copy of the monthly report form has been included for your use.

All other aspects appeared satisfactory at the time of inspection.

ORIGINAL SIGNED

Representative Signature

Inspector's Signature

Date:	October 21, 2014	Permit #:	M2013Q0017	Page No:	1
-------	------------------	-----------	------------	----------	---

ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Material has been removed from Site C stockpile.



Figure 2

Old dryer must be removed from territorial lands and taken to an authorized disposal facility.



Figure 3

A second area where quarrying has taken place at Site C.



Figure 4

A significant amount of material has been removed from the Site A stockpile.



ENVIRONMENTAL INSPECTION REPORT

Figure 5

Garbage that has been left at Site A must be removed.



Figure 6

Material has been quarried from the stockpile at the entrance to Site A.

