



Telephone: 867 874-6994  
Fax: 867 874-2460

June 24, 2021

Rowe's Construction  
25 Studney Drive  
Hay River, NT X0E 0R6

**Attention: Jack Rowe**

**File Number** MV2015Q0022  
**Type of Operation** QUARRY SITE - Existing  
**Location** Km 191.6, NWT Highway No. 1

Dear Mr. Rowe,

An inspection of the above noted operation was conducted on June 08, 2021 by Resource Management Officers Jayda Robillard and Norm McCowan.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

Jayda Robillard  
Resource Management Officer II  
Department of Lands  
South Slave Region

CC: MVLWB



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Rowe's Construction	<b>Permit Expiry Date:</b>	February 17, 2023
<b>Land Use Permit No.</b>	MV2015Q0022	<b>Previous Inspection:</b>	August 07, 2020
<b>Quarrying Permit No.</b>	20/0008	<b>Inspection Date:</b>	June 08, 2021
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 191.6, NWT Highway No. 1		
<b>Current Stage of Operation:</b>	No sign of recent activity.		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected			
	<b>Pit</b>			
Time as Permitted	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			
Equipment as Approved (Type & Size)	A			
Location as Permitted	A			
Matters not Inconsistent	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Facilities	A			
Erosion (Control or Prevention)	U(12)			
Historical / Archaeological Sites	N/A			
Wastes	A			
Methods & Techniques	A			
Fuel Storage	A			

**Explanatory Remarks –**

There has no activity in the pit in several years. A small stockpile of granular material paid for under the authority of quarry permit #2014QP0027 remains on site.

A 2 year extension to the land use permit was granted by the Mackenzie Valley Land and Water Board, the new expiry date for the permit is February 17, 2023.

Vegetation in the area is starting to grow up making it difficult to see the excavations on site. As a measure of public safety, the Inspector is requesting that Rowe's Construction place a berm around the excavations at the site. Alternatively, the sides of the excavations can be sloped to a 2:1 ratio as required by Condition 12 of your Land Use Permit. As Rowe's has equipment working in the nearby Dept of Infrastructure quarry and a camp set up within 250m of this quarry site, it is expected that this work will be completed this summer.

Date:	June 08, 2021	Permit #:	MV2015Q0022	Page No:	1
-------	---------------	-----------	-------------	----------	---



## ENVIRONMENTAL INSPECTION REPORT

\_\_\_\_\_  
Representative Signature

*Jayle Robillard*  
\_\_\_\_\_  
Inspector's Signature

Date:	June 08, 2021	Permit #:	MV2015Q0022	Page No:	2
-------	---------------	-----------	-------------	----------	---



## ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**Small stockpiled processed material.**



**Figure 2**

**Vegetation has reduced visibility of open excavations.**





## ENVIRONMENTAL INSPECTION REPORT

**Figure 3**

**Open excavation full of water requires sloping or a berm.**



**Figure 4**

**Open excavation full of water requires sloping or a berm.**





## ENVIRONMENTAL INSPECTION REPORT

Figure 5

Open excavation full of water requires sloping or a berm.

