



Telephone: 867-678-8090 ext. 24653

Fax: 867-777-2090

August 30, 2023

Yukon Gov. Dept. of Highways and Public Works  
P.O. Box 2703  
Whitehorse, YT Y1A 2C6

**Attention: Darryl Froese**

**File Number** MV2019X0027  
**Type of Operation** MISC.  
**Location** Km 6 Fiber line crew camp

Dear Darryl Froese,

An inspection of the above noted operation was conducted on August 24, 2023 by Resource Management Officer, Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen  
Resource Management Officer  
Department of Environment and Climate  
Change Land and Water  
Beaufort Delta Region

CC:

Donald Arey, Acting Regional Superintendent, Department of Environment and Climate Change Land and Water, Beaufort Delta Region  
GLWB

## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Yukon Gov. Dept. of Highways and Public Works	<b>Permit Expiry Date:</b>	August 30, 2025
<b>Land Use Permit No.</b>	MV2019X0027	<b>Previous Inspection:</b>	August 09, 2023
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	August 24, 2023
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 6 Fiber line crew camp		
<b>Current Stage of Operation:</b>	On-going		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected				
	<b>Km 6 Fiber line camp</b>				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Location as Permitted	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	U				
Wildlife and Fisheries Habitat (Protection)	A				
Historical / Archaeological Sites	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

**Explanatory Remarks – Km 6 Fiber line camp**

During the inspection at the fiber line crew camp on August 24, 2023 there were a couple of concerns observed at the site.

There was used oil in a spill tray that was that was spilling on to the ground, the spill trays should only be used as a secondary containment. Alfred Itsi indicated that they will clean up the oil and put the contents into proper containers and dispose of it into a proper facility.

There is a stack of Turbo Gel that are out in the rain and a few of the bags were broken and the contents were spilled onto the ground. It is the rainy season and the bags of Turbo Gel should be covered or stored out of the elements.

The rest of the site looks in good order.

  
\_\_\_\_\_  
Representative Signature

  
\_\_\_\_\_  
Inspector's Signature





# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2







# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4







# ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

