



Telephone: 867-678-8090 Ext. 24652

Fax: 867-777-2090

February 14, 2024

Yukon Government Department of Highways and Public Works
P.O. Box 2703
Whitehorse, YT Y1A 2C6

Attention: Darryl Froese

File Number MV2019X0027
Type of Operation MISC.
Location KM 6 Camp Site

Dear Darryl Froese,

An inspection of the above noted operation was conducted on February 13, 2024 by Resource Management Officers Bradley Voudrach and Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 Ext. 24652.

Sincerely,

Bradley Voudrach
Resource Management Officer II
Department of Environment and
Climate Change
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Environment and Climate Change, Beaufort Delta Region

AlecSandra Macdonald, Regulatory Specialist, Gwich'in Land and Water Board

Tyree Mullaney, Regulatory Specialist, Mackenzie Valley Land and Water Board

Larisse McDonald, Project Manager, Department of Highways and Public Works, Yukon Government



ENVIRONMENTAL INSPECTION REPORT

| | | | |
|--|---|---------------------------------|----------------------|
| Permittee: | Yukon Government Department of Highways and Public Works | Permit Expiry Date: | August 30, 2025 |
| Land Use Permit No.. | MV2019X0027 | Previous Inspection: | December 06, 2023 |
| Quarrying Permit No. | | Inspection Date: | February 13, 2024 |
| Contractor: | | Subcontractor: | |
| Location(s) Inspected: | KM 6 Camp Site | | |
| Current Stage of Operation: | Camp demobilized - miscellaneous material still on-site | | |
| Program Modifications Approved: | | | |

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

| Operating Condition | Aspect Inspected | | | | |
|---|---------------------------------------|--|--|--|--|
| | Dempster Fibre Project | | | | |
| Location as Permitted | A | | | | |
| Time as Permitted | A | | | | |
| Equipment as Approved (Type & Size) | A | | | | |
| Methods & Techniques | A | | | | |
| Facilities | A | | | | |
| Erosion (Control or Prevention) | U | | | | |
| Chemicals | U | | | | |
| Wildlife and Fisheries Habitat (Protection) | A | | | | |
| Wastes | A | | | | |
| Historical / Archaeological Sites | A | | | | |
| Ecological Resources | A | | | | |
| Fuel Storage | A | | | | |
| Restoration of Lands | A | | | | |
| Permits | A | | | | |
| Sections 8 to 12 / 14 to 16 M.V.L.U.R. | A | | | | |

Explanatory Remarks -

During the inspection there were no environmental concerns observed by the inspectors. There were two pieces of heavy equipment and a lot of materials for the cable installation left on-site.

The Department of Environment and Climate Change Land and Water Division would like to remind you of the issues in the "Matters For Follow Up" section of this report and to update any timelines that you may have for rectifying the concerns.



ENVIRONMENTAL INSPECTION REPORT

MATTERS FOR FOLLOW UP

September 27th, 2023 Inspection:

Remediation to surface rutting at:

KM 24
KM 184
KM 238

The surface rutting will be remediated during the 2024 spring operation.

Hydrocarbon spill clean-up at:

KM 236 - Occurrence September 26, 2023 - Waiting sample analysis for backfill -
Remediation planned for Spring 2024

KM 27.4 - Occurrence October 18, 2023 - Excavated and backfilled on October 27th

N/A

Representative Signature

B. Vandyke

Inspector's Signature

| | | | | | |
|-------|-------------------|-----------|-------------|----------|---|
| Date: | February 13, 2024 | Permit #: | MV2019X0027 | Page No: | 2 |
|-------|-------------------|-----------|-------------|----------|---|



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

One of the pieces of heavy equipment left on site.



Figure 2

The other piece of heavy equipment left on site.





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Some of the cable installation materials on site.




Figure 4

Some wooden steps and landing from the camp trailers.



| | | | | | |
|-------|-------------------|-----------|-------------|----------|---|
| Date: | February 13, 2024 | Permit #: | MV2019X0027 | Page No: | 4 |
|-------|-------------------|-----------|-------------|----------|---|