



Telephone: 867-587-7205
Fax: 867-587-2928

June 8, 2022

Cenovus Energy Inc.
225 6 Avenue SW
Calgary, AB
T2P 0M5

Attention: Greg Cave

File Number	S12X-006
Type of Operation	MISC.
Location	Water Monitoring Wells

Dear Greg Cave,

An inspection of the above-noted operation was conducted on June 06, 2022, by Manager, Resource Management Jonathan Gillingham, and Summer Student Tamara Chisholm.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the noted conditions and the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-587-7205 or by email Jonathan_Gillingham@gov.nt.ca.

Sincerely,

Jonathan Gillingham
Manager, Resource Management
Department of Lands – Sahtu Region

CC: Sahtu Land and Water Board
Trevor Bremner – Regional Superintendent – Sahtu Region
Chris Salewich – Contract Project Manager – Cenovus Energy Inc.



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Cenovus Energy Inc.	Permit Expiry Date:	December 04, 2017
Land Use Permit No.	S12X-006	Previous Inspection:	July 20, 2020
Quarrying Permit No.	N/A	Inspection Date:	June 06, 2022
Contractor:	N/A	Subcontractor:	N/A
Location(s) Inspected:	Water Monitoring Wells		
Current Stage of Operation:	Remediation		
Program Modifications Approved:	None		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Monitoring Wells				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	N/A				
Methods & Techniques	A				
Facilities	N/A				
Erosion (Control or Prevention)	A				
Chemicals	N/A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	N/A				
Historical / Archaeological Sites	A				
Ecological Resources	A				
Fuel Storage	N/A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	N/A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks:

An Inspection of the Land Use Permit S12X-006 was conducted via helicopter on June 6, 2022, by Manager, Resource Management Jonathan Gillingham, and Summer Student Tamara Chisholm. This Inspection was conducted along with Land Use Permits S20X-006 and S13A-002.

As the last Inspection Report (July 28, 2022), There are no issues with this Permit, and all required Permitted conditions have been met, and signs have been pulled. Inspector recommends this file for file closure once final plans are received and approved by the Sahtu Land and Water Board.



ENVIRONMENTAL INSPECTION REPORT

Representative Signature

Jonathan Lillingham

Inspector's Signature

Date:	June 06, 2022	Permit #:	S12X-006	Page No:	2
-------	---------------	-----------	----------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Monitoring well sites next to H-64



Figure 2

Monitoring well sites next to H-64





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Monitoring well sites next to H-64



Date:	June 06, 2022	Permit #:	S12X-006	Page No:	4
-------	---------------	-----------	----------	----------	---