



Telephone: 867-587-7205  
Fax: 867-587-2928

September 27, 2022

Great Bear Lake Lodge  
950 Bradford St.  
Winnipeg, MB R3H 0N5

**Attention: Chuk Coulter**

<b>File Number</b>	<b>S21F-002</b>
<b>Type of Operation</b>	<b>ROADS, all season (during const)</b>
<b>Location</b>	Quarry and Road

Dear Chuk Coulter,

The above-noted operation was inspected on August 23, 2022, by Manager, Resource Management Jonathan Gillingham and Summer Student Tamara Chisholm.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the noted conditions and the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-587-7205 or by email at [Jonathan\\_Gillingham@gov.nt.ca](mailto:Jonathan_Gillingham@gov.nt.ca).

Sincerely,

Jonathan Gillingham  
Manager, Resource Management  
Department of Lands – Sahtu Region

CC: Sahtu Land and Water Board  
Trevor Bremner – Regional Superintendent – Sahtu Region



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Great Bear Lake Lodge	<b>Permit Expiry Date:</b>	August 03, 2024
<b>Land Use Permit No.</b>	S21F-002	<b>Previous Inspection:</b>	New
<b>Quarrying Permit No.</b>	2020QP0013	<b>Inspection Date:</b>	August 23, 2022
<b>Contractor:</b>	N/A	<b>Subcontractor:</b>	N/A
<b>Location(s) Inspected:</b>	Quarry and Road		
<b>Current Stage of Operation:</b>	Operating		
<b>Program Modifications Approved:</b>	None		

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected			
	Quarry	Road		
Location as Permitted	A	A		
Time as Permitted	A	A		
Equipment as Approved (Type & Size)	A	A		
Methods & Techniques	A	A		
Facilities	A	A		
Erosion (Control or Prevention)	A	A		
Chemicals	A	A		
Wildlife and Fisheries Habitat (Protection)	A	A		
Wastes	A	A		
Historical / Archaeological Sites	A	A		
Ecological Resources	A	A		
Fuel Storage	A	A		
Brush Disposal	A	A		
Restoration of Lands	A	A		
Permits	A	A		
Matters not Inconsistent	A	A		
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A	A		

**Explanatory Remarks:**

An Inspection was completed on August 23, 2022, via float plane by Manager of Resource Management Jonathan Gillingham and Summer Student Tamara Chisholm. This Inspection was completed via air as bad weather was moving in. Therefore, the following Inspection should be completed on the ground.

**Road:**

From the air, the road was in good condition. The last report (September 25, 2020) showed no environmental issues or concerns with the road. The Permittee is currently compliant with all Permitted requirements.



## ENVIRONMENTAL INSPECTION REPORT

**Quarry:**

During the Inspection, the quarry had some equipment staged (screener, grader, and a haul truck). However, the quarry was not operating during the Inspection. Inspector did not observe if fuel was stored at the quarry during the Inspection or the use of drip trays under the staged equipment. The following Inspection should be conducted on the ground.

**General Comments:**

Fuel is stored on the airstrip on site; this area was not inspected thoroughly due to weather constraints. The following Inspection will be conducted on the ground to confirm if all permitted conditions are in an acceptable state.

\_\_\_\_\_  
Representative Signature

  
\_\_\_\_\_  
Inspector's Signature

Date:	August 23, 2022	Permit #:	S21F-002	Page No:	2
-------	-----------------	-----------	----------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

Aerial of quarry



**Figure 2**

Aerial of road



**Figure 3**

Aerial of quarry and road

