



October 20, 2021

File Number **W2016E0004**
Type of Operation **All Weather Road Construction**
Location **Tlicho All Season Road (TASR)**

An inspection of the access roads into Pit 2B and Pit 3 was conducted on October 19, 2021 by Inspectors Clint Ambrose and Brandon Bradbury. The inspection was carried out to confirm the removal & re-contouring of the two berms on the access road to Pit 2B and the scarification & removal of two items from the access road to Pit 3.

This report and attached images confirm that the work was conducted in a manner to comply with the operating conditions annexed to the quarry permits and land use permit W2016E0004.

No further work is required at either of the aforementioned locations.

Regards,

Clint Ambrose
Manager, Resource Management (Inspector)
GNWT – Department of Lands



INSPECTION IMAGES

Figure 1

The berm on the eastern access to Pit 2B has been flattened and contoured.



Figure 2

The berm on the western access to Pit 2B has been flattened and contoured.





INSPECTION IMAGES

Figure 3

Looking north along the access road into Pit 3.



Figure 4

The hard packed center line of the Pit 3 access road has been scarified and items from the previous inspection removed.

