



Telephone: 867-767-9187 ex.24187  
Fax: 867-873-6230

March 4, 2025

Alexis Campbell  
Government of the Northwest Territories – Department of infrastructure  
Box 1320  
Yellowknife NT X1A2L9

**Attention: Alexis Campbell**

<b>File Number</b>	<b>W2021L8-0002</b>
<b>Type of Operation</b>	<b>CLASS B -</b>
<b>Location</b>	<b>Whati Access Road, NT</b>

Dear Ziaur Rahman,

An inspection of the above noted operation was conducted on October 16, 2024 by Water Resource Officer Nahum Lee. Enclosed is a copy of the inspection report.

No concerns were noted during the inspection. If you have any questions, please contact me at 867-767-9187 ext. 24193.

Sincerely,

Nahum Lee  
Water Resource Officer  
Environment and Climate Change  
North Slave Region

Cc: Scott Stewart – North Slave Regional Superintendent – ECC  
Rick Walbourne – Director, Water Regulatory – ECC  
Wendy Bidwell – Senior Water Resource Officer – ECC  
Ziaur Rahman – GNWT – INF



### WATER USE INSPECTION REPORT

<b>LICENCE #:</b>	W2021L8-0002	<b>EXPIRY DATE:</b>	August 01, 2026
<b>LICENCEE:</b>	GNWT – INF	<b>PREVIOUS INSPECTION:</b>	Initial
<b>COMPANY REP:</b>	N/A	<b>INSPECTION DATE:</b>	October 16, 2024

**GENERAL CONDITIONS/REPORTS/PLANS**

Indicate:    **A - Acceptable**        **U - Unacceptable**        **N/A - Not Applicable**    **N/I - Not Inspected**

C &R Plan	A	Records & Reporting	A	Final Report	N/I
Geotechnical Inspection	N/A	Posting, Signage	N/A	Contingency Plan	A
Restorations Activities	A	Spills	A	O&M Plan	A
Maintenance	A	Modifications	N/A	Annual Report	A

**General Condition Comments:**

The Whati Access Road was improved during the summer and fall of 2024 with the installation of a bridge and the use of water for the purposes of dust suppression. No concerns were noted with this operation. Photos 1 and 2 show the bridge construction and erosion control measures taken as a result.

**WASTE DISPOSAL – SOLID WASTE**

Disposal Method		Removal					
Open Dump	No	Landfill	No	Burn & Landfill	No	Underground	No
Offsite Removal	Yes	Other					
Owner / Operator	Community Government of Gamètì						

Indicate:    **A - Acceptable**        **U - Unacceptable**        **N/A - Not Applicable**    **N/I - Not Inspected**

Runoff Diversion	N/A	SNP Samples Collected	No
------------------	-----	-----------------------	----

**Solid Waste Comments:**

Solid and hazardous waste from the project is being removed from site and disposed of at registered facilities. No concerns with waste disposal were identified.

Inspectors Signature:

---



## WATER USE INSPECTION REPORT

Photo 1: Bridge installation.



Photo 2: Completed installation. Rip rap has been installed in the streambed to prevent erosion.

