



March 17, 2023

NWT Power Corporation  
Box 2250  
YELLOWKNIFE, NT X1A 2P7

**Re: Land Use Permit W2021Q0011  
Quarrying / Winter Roads / Camps  
Snare Forks to Kilometre 12 of the Wekweètì Winter Road, NT**

Dear Mr. Miller,

An inspection of the winter road from Kilometre 12 of the Wekweètì Winter Road to the Snare Forks Hydro Facility was conducted by Inspectors Clint Ambrose and Karine Gignac on March 16<sup>th</sup>, 2023. The inspection was carried out to ensure operating conditions annexed to the above noted land use permit are being adhered to during this land use operation. The Inspectors met Mr. Barry Franklin (Contractor) on the winter road and all findings of the inspection were discussed.

Winter road construction is nearing completion with only a minor number of touch-ups to complete prior to the demobilization of equipment from the land use area. No major concerns were noted during the inspection and the Inspector's anticipate ongoing road maintenance to be conducted by the Permittee throughout the 2023 Operating Season to maintain compliance with Condition #11 of the permit. Your copy of the Environmental Inspection Report is enclosed and should be self-explanatory.

If you have any questions or concerns, please contact the undersigned at (867) 767-9188 or Ms. Karine Gignac at (867) 767-9187 ext. 24189.

Sincerely,

Clint Ambrose  
Manager, Resource Management (Inspector)  
North Slave Regional Office  
GNWT – Department of Lands

cc: WLWB  
Tlicho Investment Corporation & Group of Companies. – via email  
NTPC – via email  
Weatherby Trucking Ltd. – via email





## ENVIRONMENTAL INSPECTION REPORT

Permittee:	NWT Power Corporation	Inspection Date – March 16 <sup>th</sup> , 2023
------------	-----------------------	---

		Permit Expiry Date	Last Previous Inspection
Land Use Permit No.	W2021Q0011	January 3 <sup>rd</sup> , 2027	March 1 <sup>st</sup> , 2023
Quarry Permit No.			
Contractor:	Tlicho Investment Corporation & Group of Companies	Sub-Contractor:	Weatherby Trucking Ltd.

Location(s) Inspected:	The 12.3 km winter road from the Wekweèti winter road (Km 12) to the Snare Forks Hydro Facility.
------------------------	--

Current Stage of Operation:	Winter road construction is nearing completion and “punch outs” on the portages will be repaired while equipment is still present in the land use area.
-----------------------------	---

Program Modifications Approved:	
---------------------------------	--

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable

	Operating Condition	Aspect Inspected			
		Winter Road			Condition
A	Location and Area	A			
B	Time	A			
C	Type and Size of Equipment	A			
D	Methods and Techniques	A*			#11 – Winter Roads
E	Type, Location, Capacity and Operation of All Facilities	A			
F	Control or Prevention of Ponding of Water, Flooding, Erosion, Slides and Subsidence of Land	A			
G	Use, Storage, Handling and Ultimate Disposal of Any Chemical or Toxic Material	A			
H	Wildlife and Fisheries Habitat	A			
I	Storage, Handling and Disposal of Refuse or Sewage	A			
J	Protection of Historical, Archeological and Burial Sites	A			
K	Objects and Places of Recreational, Scenic or Ecological Value	N/A			
L	Security Deposit	N/A			
M	Fuel Storage	A			
N	Methods and Techniques for Debris and Brush Disposal	A			
O	Restoration of the Lands	A			
P	Display of Permits and Permit Numbers	A			
Q	Matters Not Inconsistent with the Regulations	A			
R	Sections 8 to 16 M.V.L.U.R.	A			



## ENVIRONMENTAL INSPECTION REPORT Pg. 2

Date: March 16 <sup>th</sup> , 2023	Permit #: W2021Q0011
-------------------------------------	----------------------

Explanatory Remarks
<p>An inspection of the winter road from kilometre twelve (12) of the Wekweètì Winter Road to the Snare Forks Hydro Facility was conducted by Inspectors Clint Ambrose and Karine Gignac on March 16<sup>th</sup>, 2023. The inspection was carried out to ensure operating conditions annexed to the above noted land use permit are being adhered to during this land use operation. The Inspectors met with Mr. Barry Franklin (Contractor) on site and all findings of the inspection were discussed.</p> <p>Winter road construction was nearing completion at the time of the inspection and as seen in Figure 1, the entire running surface of the road has been iced in from shoulder-to-shoulder to meet the requirements of Condition #11 of the land use permit. The cooperation of the Contractor &amp; Sub-Contractor is appreciated by Inspectors, and it is anticipated that road maintenance will be conducted throughout the 2023 Operating Season to address “punch outs” like the one viewed in Figure 2.</p> <p>Prior to the cessation of winter road operations by the Permittee, the Inspector must be notified as per Condition #9 so that a final inspection can be scheduled.</p>

Completed off Site  
Representative's Signature

Clint Ambrose  
Inspector

  
Inspector's Signature



## ENVIRONMENTAL INSPECTION REPORT

**Figure 1**

**Winter road construction from the Wekweèti Winter Road to the Snare Hydro Facility is complete.**



**Figure 2**

**An example of a “punch out” on a portage that must be repaired. Winter road maintenance must occur throughout the 2023 operating season.**



Date:	March 16, 2023	Permit #:	W2021Q0011	Page No:	1
-------	----------------	-----------	------------	----------	---