



March 23, 2022

NWT Power Corp
4 Capital Drive
Hay River, NT X0E 1G2

Attention: Matthew Miller

File Number W2021Q0011
Type of Operation Winter Road
Location Snare Hydroelectric Facility

Dear Mr. Miller,

An inspection of the winter road from Kilometre 12 of the Wekweètì Road to the Snare Forks Hydro Facility was conducted by Inspectors Clint Ambrose and Karine Gignac on March 22nd, 2022. The inspection was carried out to ensure operating conditions annexed to the above noted land use permit are being adhered to during this land use operation.

Winter road construction is complete and all equipment has been demobilized from the land use area. The Inspectors are pleased to report that sufficient icing was present on the portages to meet the requirements of Condition #11 of the land use permit and no concerns were noted during the inspection.

The cooperation of the Permittee and Contractor is appreciated and it is anticipated that the condition of the winter road will be diligently monitored to ensure compliance with all operating conditions of the permit continues.

As per Condition #9 of the land use permit, please ensure adequate notification is provided to the Inspectors prior to the seasonal closure of the winter road.

If you have any questions or concerns, please contact the undersigned at (867) 767-9188 or Ms. Karine Gignac at (867) 767-9187 ext. 24189.

Sincerely,

Clint Ambrose
Manager, Resource Management (Inspector)
North Slave Regional Office
GNWT – Department of Lands

cc: WLWB
Weatherby Trucking Ltd. – via email



ENVIRONMENTAL INSPECTION REPORT

Figure 1

Example of a completed portage. Sufficient icing of the ground surface was present.




Figure 2

Another view of the winter road which was scheduled to be dragged the day of the inspection.

