



July 6th, 2022

TliCho Government
PO Box 412
Behchoko, NT X0E 0Y0

**Re: Land Use Permit W2021X0001
TliCho Government Misc (Fibre Optic)**

Dear Mark Poskitt,

An inspection of the fibre optic line operation from km 0-89 of the Highway #9 was conducted by Inspectors Clint Ambrose and Karine Gignac on July 5th, 2022. The inspection was carried out to ensure operating conditions annexed to the above noted land use permit are being adhered to during this land use operation.

The Inspectors were pleased with the manner in which the operation is being conducted and no concerns were noted with the fibre optic line operation along Highway #9. Your copy of the Environmental Inspection Report is enclosed and should be self-explanatory.

If you have any questions or concerns, please contact the undersigned at (867) 767-9187 ext. 24189 or Mr Clint Ambrose at (867) 767-9188.

Sincerely,

Karine Gignac
Resource Management Officer II (Inspector)
North Slave Regional Office
GNWT – Department of Lands

cc: MVLWB
Peter Kiewit Sons ULC- via email
IFS- via email



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Tlicho Government	Inspection Date – July 5 th , 2022
------------	-------------------	---

		Permit Expiry Date	Last Previous Inspection
Land Use Permit No.	W2022X0001	April 25 th , 2026	June 1 st , 2022
Land Use Permit No.			
Quarry Permit No.			
Contractor:	Peter Kiewit Sons ULC	Subcontractor:	IFS

Location(s) Inspected:	Fibre optic line along Highway #9
------------------------	-----------------------------------

Current Stage of Operation:	Fibre optic line jetting (Km 84-96), splicing (Km 14-84) and fusion (Km 45-96) are being conducted along the road.
-----------------------------	--

Program Modifications Approved:	
---------------------------------	--

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable

	Operating Condition	Aspect Inspected			
		Fibre optic			Condition
A	Location and Area	A			
B	Time	A			
C	Type and Size of Equipment	A			
D	Methods and Techniques	A			
E	Type, Location, Capacity and Operation of All Facilities	A			
F	Control or Prevention of Ponding of Water, Flooding, Erosion, Slides and Subsidence of Land	A			
G	Use, Storage, Handling and Ultimate Disposal of Any Chemical or Toxic Material	A			
H	Wildlife and Fisheries Habitat	A			
I	Storage, Handling and Disposal of Refuse or Sewage	A			
J	Protection of Historical, Archeological and Burial Sites	A			
K	Objects and Places of Recreational, Scenic or Ecological Value	N/A			
L	Security Deposit	A			
M	Fuel Storage	A			
N	Methods and Techniques for Debris and Brush Disposal	A			
O	Restoration of the Lands	A			
P	Display of Permits and Permit Numbers	A			
Q	Matters Not Inconsistent With the Regulations	A			
R	Sections 8 to 16 M.V.L.U.R.	A			



ENVIRONMENTAL INSPECTION REPORT Pg. 2

Date: July 5 th , 2022	Permit #: W2021X0001
-----------------------------------	----------------------

Explanatory Remarks
<p>An inspection of the fibre optic line jetting and splicing operation from km 0-89 of the Highway #9 was conducted by Inspectors Clint Ambrose and Karine Gignac on July 5th, 2022. The inspection was carried out to ensure operating conditions annexed to the above noted land use permit are being adhered to during this land use operation.</p> <p><u>Km 0-89 fibre optic line</u></p> <p>The inspectors are pleased with the communication and the regular updates provided on the operations status of the fibre optic line. At the time of inspection, jetting was under way between km 84-96, splicing from km 14-84 and fusion being conducted at km 45-96 of the Highway #9. No environmental concerns were noted along the road for this operation, and there were no rutting or gouging observed where equipment appeared to be working.</p> <p>Overall, the Inspectors were pleased with the manner in which this land use operation is conducted and no concerns were noted. It is anticipated that the Inspectors will continue to receive updates on the various operations status and the Permittee's and the Contractor's cooperation is appreciated.</p>

Completed off Site
Representative's Signature

Karine Gignac
Inspector


Inspector's Signature



Figure 1
Pull box at Km #89.



Figure 2
The Km #89 pull box, showing very minimal disturbance.





Figure 3
Generator.



Figure 4
Reel of fibre optic line at Km 89.

