



Indian and Northern Affairs Canada  
Affaires Canada  
www.inac.gc.ca

..ffaires indiennes  
et du Nord Canada  
www.ainc.gc.ca

Telephone: (867)777-3361  
Fax: (867)777-2090

North Mackenzie District  
P.O. Box 2100  
INUVIK, NT X0E 0T0

*Your file - Votre référence*

02.09.05

*Our file - Notre référence*

Arctic Tire (1980) Ltd.  
P.O. Box 2238  
INUVIK, NT X0E 0T0

Attention: Brian McCarthy

Dear Mr. McCarthy

**Re: Land Use Permit G02Q005  
Quarrying Operation - km 251.2 Dempster Highway**

On 02.09.03, Conrad Baetz, Land Use Inspector, inspected your land use operation conducted under the above referenced Land Use Permit.

Enclosed is a copy of the Inspection Report. Please note the Explanatory Remarks section of this report. Your attention to this matter is greatly appreciated.

If you have any questions do not hesitate to call our office.

Yours truly

R.A. Cockney  
District Manager

cc: Resource Management Officer III, Inuvik  
Gwich'in Land and Water Board

Canada



### ENVIRONMENTAL INSPECTION REPORT

Permittee:	Arctic Tire (1980) Ltd., P.O. Box 2238, Inuvik, NWT X0E 0T0
------------	---

		Permit Expiry Date	Last Previous Inspection
Land Use Permit No.	G02Q005	Oct. 31, 2004	Initial
Quarrying Permit No.	2002QP0069		
Contractor:		Subcontractor:	

Location(s) Inspected:	Km 251 quarry site - Dempster Highway
------------------------	---------------------------------------

Current Stage of Operation:	Quarrying completed
-----------------------------	---------------------

Program Modifications Approved:	N.A. _____
---------------------------------	------------

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

	Operating Condition	Aspect Inspected			
		Quarry			
A	Location as Permitted	A			
B	Timing as Permitted	A			
C	Equipment as Approved (Type & Size)	A			
D	Methods & Techniques	A			
E	Facilities	A			SEE NOTE
F	Erosion (Control or Prevention)	A			
G	Chemicals	A			
H	Wildlife and Fisheries Habitat (Protection)	A			
I	Wastes	---			
J	Historical / Archaeological Sites	---			
K	Ecological Resources	----			
L	Security Deposit	----			
M	Fuel Storage	----			
N	Brush Disposal	-----			
O	Restoration of Lands	-----			
P	Permits	----			
Q	Matters Not Inconsistent				
R	Sections 8 to 12 / 14 to 16 M.V.L.U.R.				
S	Quarrying Methods				

Explanatory Remarks (attach page 2 if necessary)
--

Garbage laying on site, couple of 5 gal oil jugs, cardboard box. Drill holes are quite large and are not plugged, please see that these are plugged to prevent an accident. What are the plans for these holes? Also like to know why this area was not utilized as per the inspectors instructions at an earlier site visit?

Inspector's Signature 