



Telephone: 867-678-8090 Ext. 24652

Fax: 867-777-2090

May 31, 2023

NWT Energy Corporation (03) Ltd.
4 Capital Drive
Hay River, NT XOE 1G2

Attention: Salah Abouelnaga

File Number G18X005
Type of Operation MISC.
Location High Point Access and Tower Pad

Dear Salah Abouelnaga,

An inspection of the above noted operation was conducted on May 30, 2023 by Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 Ext. 24652.

Sincerely,

Bradley Voudrach
Resource Management Officer I
Department of Environment and
Climate Change
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Environment and Climate Change,
Beaufort Delta Region

AlecSandra Macdonald, Regulatory Specialist, Gwich'in Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF April 25, 2023

Review and implement the EROSION AND SEDIMENT CONTROL PLAN and the WASTE MANAGEMENT PLAN.

Permittee:	NWT Energy Corporation (03) Ltd.	Permit Expiry Date:	November 26, 2025
Land Use Permit No.	G18X005	Previous Inspection:	April 25, 2023
Quarrying Permit No.	2021QP0032 - for 300,000cm	Inspection Date:	May 30, 2023
Contractor:		Subcontractor:	
Location(s) Inspected:	High Point Access and Tower Pad		
Current Stage of Operation:	Active		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Wind Tower access and pad				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	U				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	U				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Sections 12 to 19 T.L.U.R.	A				
Location as Permitted	A				
Wastes	U				

Explanatory Remarks -

Wind Tower Access and Pad:

During the inspection it was observed that the concerns mentioned in the previous inspection reports have not yet been rectified but, NWT Energy Corporation told the Inspector that they would be getting an excavator to remove the remaining used geotech rolls and geotech along the Right-of-Way (ROW).

The ROW has not yet been built up to grade as a majority (if not all) the construction efforts were focused on the tower at the moment.



ENVIRONMENTAL INSPECTION REPORT

The Department of Environment and Climate Change would like to remind NWT Energy Corporation to notify our office when the plans mentioned in the April 27th inspection report begin being implemented at the site.

Representative Signature

B. Vandyke

Inspector's Signature

Date:	May 30, 2023	Permit #:	G18X005	Page No:	2
-------	--------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

A photo of the road, taken from the entrance.



Figure 2

A photo with some of the used geotech rolls and geotech still on site.



Date:	May 30, 2023	Permit #:	G18X005	Page No:	3
-------	--------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 3
A photo of the tower.



Date:	May 30, 2023	Permit #:	G18X005	Page No:	4
-------	--------------	-----------	---------	----------	---