



Telephone: 867-777-8907
Fax: 867-777-2090

May 27, 2022

NWT Energy Corporation (03) Ltd.
4 Capital Drive
Hay River, NT XOE 1G2

Attention: Bruno Pereira

File Number G18X005
Type of Operation MISC.
Location Wind tower access and tower pad

Dear Bruno Pereira,

An inspection of the above noted operation was conducted on May 26, 2022 by Resource Management Officer II Herbert Allen and Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:
Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	NWT Energy Corporation (03) Ltd.	Permit Expiry Date:	November 26, 2025
Land Use Permit No.	G18X005	Previous Inspection:	May 17, 2022
Quarrying Permit No.	2021QP0032 - for 300,000cm	Inspection Date:	May 26, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	Wind tower access and tower pad		
Current Stage of Operation:	on-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Wind Tower access and pad				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Sections 12 to 19 T.L.U.R.	A				

Explanatory Remarks -

Wind Tower access and pad:

During the inspection on May 26, 2022 at the wind tower access and wind tower site there were no concerns observed by the inspector.

There were engineers from Golder monitoring work in progress with the drilling and installation of the pilings for the wind tower. Tundra Drilling are working on drilling and installing of the pilings for the wind tower and they were about half way complete, there were 12 pilings installed out of 25 that were at the site. There are a lot of equipment parked and working at the site and they should be monitored for spills and leaks, there were spill trays under some of the equipment.

The work on widening and building up the access road is still in progress and seem to be moving forward. Culverts may need to be install soon as there is water ponding along side of the access road in different sections.

Department of Lands would like a copy of the engineering drawings and plans for the next stages in the project to ensure we are kept up to speed and the inspectors know what to expect on future

Date:	May 26, 2022	Permit #:	G18X005	Page No:	1
-------	--------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

inspections.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6



Date:	May 26, 2022	Permit #:	G18X005	Page No:	5
-------	--------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 7



Figure 8



Date:	May 26, 2022	Permit #:	G18X005	Page No:	6
-------	--------------	-----------	---------	----------	---