



Telephone: 867 777-8900

Fax: 867-777-2090

April 1, 2022

NWT Energy Corporation (03) Ltd.
4 Capital Drive
Hay River, NT XOE 1G2

Attention: Bruno Pereira

File Number	G18X005
Type of Operation	MISC.
Location	High wind Access and quarry site

Dear Bruno Pereira,

An inspection of the above noted operation was conducted on March 31, 2022 by Manager, Resource Management Donald Arey and Regional Superintendent Dan Carmichael.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Sincerely,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Beaufort Delta Region
GLWB

Bag Service #1, Inuvik, NT XOE OT0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	NWT Energy Corporation (03) Ltd.	Permit Expiry Date:	November 26, 2025
Land Use Permit No.	G18X005	Previous Inspection:	March 15, 2022
Quarrying Permit No.	2021QP0032 - for 300,000cm	Inspection Date:	March 31, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	High wind Access and quarry site		
Current Stage of Operation:	ongoing		
Program Modifications Approved:	nil		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	High Wind Access and Km 251				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Ecological Resources	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

High Wind Access and Km 251:

During this inspection it was observed that work is under way for laying granular material onto the access road. All matters to this was observed as acceptable.

Quarrying was also being done at Km 251 where the material is taken from, no environmental concerns were observed at this location as well.

Please ensure that your LUP Terms and Conditions are followed as well the Quarry Permit conditions, in particular for item 5, 7, 8, 9, 10 and 11.



ENVIRONMENTAL INSPECTION REPORT

MATTERS FOR FOLLOW UP

LUP Terms and Conditions and the Quarry Permit Terms and conditions are to be followed.

M/A

Representative Signature

[Handwritten Signature]

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4
Km 251

