



Telephone: 867-678-8090 Ext. 24652

Fax: 867-777-2090

May 31, 2023

GNWT Department of Infrastructure  
Bag Service #1, 106 Veterans Way  
Inuvik, NT X0E 0T0

**Attention: Allan Hamilton**

**File Number** G20H006  
**Type of Operation** CAMPS - < 50 Man Camp  
**Location** James Creek Highway Maintenance Camp

Dear Allan Hamilton,

An inspection of the above noted operation was conducted on May 30, 2023 by Resource Management Officer I Bradley Voudrach and Manager, Resource Management Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 Ext. 24652.

Sincerely,

Bradley Voudrach  
Resource Management Officer I  
Department of Environment and  
Climate Change  
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Environment and Climate Change,  
Beaufort Delta Region

AlecSandra Macdonald, Regulatory Specialist, Gwich'in Land and Water Board



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	August 05, 2023
<b>Land Use Permit No.</b>	G20H006	<b>Previous Inspection:</b>	February 21, 2023
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	May 30, 2023
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	James Creek Highway Maintenance Camp		
<b>Current Stage of Operation:</b>	Active		
<b>Program Modifications Approved:</b>			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected


Operating Condition	Aspect Inspected					
	<b>James Creek Km 14.2</b>					
Equipment as Approved (Type & Size)	A					
Methods & Techniques	A					
Chemicals	U					
Wildlife and Fisheries Habitat (Protection)	A					
Wastes	A					
Fuel Storage	A					
Restoration of Lands	A					
Permits	A					
Matters not Inconsistent Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A					
Location as Permitted	A					
Time as Permitted	A					

**Explanatory Remarks -**

**James Creek Km 14.2:**

During the inspection there was one concern observed by the inspector. Behind the shop there were four (4) pails of hydrocarbon with no secondary containment and one of them were not sealed/covered. The Department of Environment and Climate Change Land and Water division would like to recommend that the Waste Management Plan be reviewed by all applicable parties to eliminate any potential spills. All other aspects of the operation were satisfactory.

\_\_\_\_\_  
Representative Signature

  
Inspector's Signature

Date:	May 30, 2023	Permit #:	G20H006	Page No:	1
-------	--------------	-----------	---------	----------	---






# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**The four pails of hydrocarbon behind the shop.**



**Figure 2**

**One of the pails that were not covered.**







# ENVIRONMENTAL INSPECTION REPORT

**Figure 3**  
**Aerial view of the maintenance camp site.**



Date:	May 30, 2023	Permit #:	G20H006	Page No:	3
-------	--------------	-----------	---------	----------	---