



Telephone: 867-678-8090 Ext. 24652
Fax: 867-777-2090

August 11, 2023

GNWT Department of Infrastructure
Bag Service #1, 106 Veterans Way
Inuvik, NT X0E 0T0

Attention: Allan Hamilton

File Number G20H006
Type of Operation CAMPS - < 50 Man Camp
Location James Creek Highway Maintenance Camp

Dear Allan Hamilton,

An inspection of the above noted operation was conducted on August 09, 2023 by Resource Management Officer I Bradley Voudrach and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-678-8090 Ext. 24652.

Sincerely,

Bradley Voudrach
Resource Management Officer I
Department of Environment and
Climate Change
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Environment and Climate Change,
Beaufort Delta Region

AlecSandra Macdonald, Regulatory Specialist, Gwich'in Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	August 05, 2023
Land Use Permit No.	G20H006	Previous Inspection:	July 18, 2023
Quarrying Permit No.		Inspection Date:	August 09, 2023
Contractor:		Subcontractor:	
Location(s) Inspected:	James Creek		
Current Stage of Operation:	On-Going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	James Creek Km 14.2				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				
Time as Permitted	A				

Explanatory Remarks -
James Creek Km 14.2:
 During the inspection there were no concerns observed by the Inspectors. The site has been well maintained in terms of fuel storage and solid waste disposal.

 Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

The fuel storage tank.



Figure 2

The back side of the fuel storage tank.





ENVIRONMENTAL INSPECTION REPORT

Figure 3
The shop entrance.



Figure 4
Road signs and other supplies for the operation.



Date:	August 09, 2023	Permit #:	G20H006	Page No:	3
-------	-----------------	-----------	---------	----------	---