



Telephone: 867-678-8090 Ext. 24652  
Fax: 867-777-2090

December 16, 2022

GNWT Department of Infrastructure  
Bag Service #1, 106 Veterans Way  
Inuvik, NT X0E 0T0

**Attention: Mosiul Alam**

**File Number** G20H006  
**Type of Operation** CAMPS - < 50 Man Camp  
**Location** James Creek Highway Maintenance Camp

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on December 14, 2022 by Resource Management Officer I Bradley Voudrach and Manager, Resource Management Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 Ext. 24652.

Sincerely,

Bradley Voudrach  
A/ Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Lands, Beaufort Delta Region  
AlecSandra Macdonald, Regulatory Specialist, Gwich'in Land and Water Board



### ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	August 05, 2023
<b>Land Use Permit No.</b>	G20H006	<b>Previous Inspection:</b>	October 19, 2022
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	December 14, 2022
<b>Contractor:</b>	LJ's Septic Services and Contracting Ltd.	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	James Creek Highway Maintenance Camp		
<b>Current Stage of Operation:</b>	Active		
<b>Program Modifications Approved:</b>			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	James Creek Km 14.2				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Chemicals	U				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				

**Explanatory Remarks -**

**James Creek Km 14.2:**

During the inspection it was observed that there was one unacceptable condition related to the operation. Near the entrance there were two 205-liter drums and one smaller container that had waste oil/hydrocarbon (see figure 1). The Highway Maintenance operation and Terms and Conditions of the permit do not allow for any waste oil storage on-site.

All other aspects of the operation were satisfactory at the time of inspection.

**MATTERS FOR FOLLOW UP**

Waste oil observed on December 14, 2022 inspection.

\_\_\_\_\_  
Representative Signature

*B. Vaudelle*  
\_\_\_\_\_  
Inspector's Signature

Date:	December 14, 2022	Permit #:	G20H006	Page No:	1
-------	-------------------	-----------	---------	----------	---



### ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**Aerial view of the site, taken from the Government of the Northwest Territories Administration of the Territorial Lands Act System or GNWT ATLAS.**



Date:	December 14, 2022	Permit #:	G20H006	Page No:	2
-------	-------------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

**Figure 2**

The waste oil drums referred to in the comments section of this report.



**Figure 3**

Spill kit near the fuel storage tanks.




Date:	December 14, 2022	Permit #:	G20H006	Page No:	3
-------	-------------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

**Figure 4**  
**The fuel supply pump locked out.**



**Figure 5**  
**The front of the shop.**



Date:	December 14, 2022	Permit #:	G20H006	Page No:	4
-------	-------------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

**Figure 6**  
**The camps and some of the equipment.**



Date:	December 14, 2022	Permit #:	G20H006	Page No:	5
-------	-------------------	-----------	---------	----------	---