



Telephone: 867-678-8090 Ext. 24652

Fax: 867-777-2090

February 10, 2023

GNWT Department of Infrastructure  
Bag Service #1, 106 Veterans Way  
Inuvik, NT X0E 0T0

**Attention: Mosiul Alam**

**File Number** G20H006  
**Type of Operation** CAMPS - < 50 Man Camp  
**Location** James Creek Highway Maintenance Camp

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on February 09, 2023 by Resource Management Officer I Bradley Voudrach and Manager, Resource Management Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-678-8090 Ext. 24652.

Sincerely,

**Bradley Voudrach**  
Resource Management Officer I  
Department of Lands  
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Lands, Beaufort Delta Region  
AlecSandra Macdonald, Regulatory Specialist, Gwich'in Land and Water Board



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	August 05, 2023
<b>Land Use Permit No.</b>	G20H006	<b>Previous Inspection:</b>	January 05, 2023
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	February 09, 2023
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	James Creek Highway Maintenance Camp		
<b>Current Stage of Operation:</b>	Active		
<b>Program Modifications Approved:</b>			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	<b>James Creek Km 14.2</b>				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				

**Explanatory Remarks -**

James Creek Km 14.2:  
All aspects were satisfactory at the time of inspection. There were no changes from the last inspection on January 05, 2023.

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature



## ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**The fuel storage.**



**Figure 2**

**The front of the shop.**





## ENVIRONMENTAL INSPECTION REPORT

**Figure 3**  
**The south-end entrance.**

