



Telephone: 867-678-8090 Ext. 24652

Fax: 867-777-2090

January 6, 2023

GNWT Department of Infrastructure
Bag Service #1, 106 Veterans Way
Inuvik, NT X0E 0T0

Attention: Mosiul Alam

File Number G20H006
Type of Operation CAMPS - < 50 Man Camp
Location James Creek Highway Maintenance Camp

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on January 05, 2023 by Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-678-8090 Ext. 24652.

Sincerely,

Bradley Voudrach
A/ Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Lands, Beaufort Delta Region
AlecSandra Macdonald, Regulatory Specialist, Gwich'in Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	August 05, 2023
Land Use Permit No.	G20H006	Previous Inspection:	December 14, 2022
Quarrying Permit No.		Inspection Date:	January 05, 2023
Contractor:		Subcontractor:	
Location(s) Inspected:	James Creek Highway Maintenance Camp		
Current Stage of Operation:	Active		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	James Creek Km 14.2				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				

Explanatory Remarks -
 James Creek Km 14.2:
 During the inspection there were no spills observed by the inspector. The waste oil that was observed during the previous inspection was removed from the site. All aspects were satisfactory at the time of inspection.

 Representative Signature

B. Vaudelle

 Inspector's Signature

Date:	January 05, 2023	Permit #:	G20H006	Page No:	1
-------	------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Overlooking the site from the entrance.



Figure 2

The south access road.



Date:	January 05, 2023	Permit #:	G20H006	Page No:	2
-------	------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT


Figure 3

Location where the 205-liter waste oil drums were during the last inspection.



Figure 4

The fuel storage pump.



Date:	January 05, 2023	Permit #:	G20H006	Page No:	3
-------	------------------	-----------	---------	----------	---