



Telephone: 867-777-8907  
Fax: 867-777-2090

June 11, 2021

GNWT Department of Infrastructure  
Bag Service #1, 106 Veterans Way  
Inuvik, NT X0E 0T0

Attention: **Mosiul Alam**

**File Number** G20H006  
**Type of Operation** CAMPS  
**Location** Km 14.2

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on June 10, 2021 by Resource Management Officer II Herbert Allen and Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

**Herbert Allen**  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC:

Dan Carmicheal, Regional Superintendent, Department of Lands, Beaufort Delta Region  
GLWB



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	August 05, 2021
<b>Land Use Permit No.</b>	G20H006	<b>Previous Inspection:</b>	April 22, 2021
<b>Quarrying Permit No.</b>	68	<b>Inspection Date:</b>	June 10, 2021
<b>Contractor:</b>	LJ's	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 14.2		
<b>Current Stage of Operation:</b>	On-going		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected
	<b>James Creek Km 14.2</b>
Location as Permitted	A
Time as Permitted	A
Equipment as Approved (Type & Size)	A
Methods & Techniques	A
Chemicals	U
Wildlife and Fisheries Habitat (Protection)	A
Wastes	A
Fuel Storage	A
Restoration of Lands	A
Permits	A
Matters not Inconsistent	A
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A

**Explanatory Remarks - James Creek Km 14.2:**

During the inspection on June 10, 2021 at the James Creek Maintenance camp there was only a couple of concerns.

There are 2 spills located on the ground at the site, 1 in front of the garage door closest to the camp building and the other is at the west side of the site near the excavator and the cat that's parked by the contaminated soil site.

There were 2 tractor trailer gravel trucks belonging to Allen's Services parked at the south access. There was also a shipping container, a small container with a door and a car by the trucks.

On our way back to Inuvik we met up with the Allen's Services crew on the road and they were in a flat bed tractor trailer truck and they indicated they were just on their way to James Creek to pick up the trucks but we forgot to mention the containers and the car. We are assuming they will be picking up the containers and the car as they were beside their trucks and they had the flat bed. We will follow up with the containers and the car during our next inspection.

The rest of the site is clean and looks in good order and there was no one on site during the inspection.

*NA*

Representative Signature

*[Handwritten Signature]*

Inspector's Signature

Date:	June 10, 2021	Permit #:	G20H006	Page No:	1
-------	---------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**



**Figure 2**





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





# ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6





# ENVIRONMENTAL INSPECTION REPORT

Figure 7




Figure 8

