



Telephone: 867-678-8090 ext. 24653

Fax: 867-777-2090

July 19, 2023

GNWT Department of Infrastructure  
Bag Service #1, 106 Veterans Way  
Inuvik, NT X0E 0T0

**Attention: Mosiul Alam**

**File Number** G20H006  
**Type of Operation** CAMPS  
**Location** James Creek Km 14.2

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on July 18, 2023 Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen  
Resource Management Officer II  
Department of Environment and Climate  
Change Land and Water  
Beaufort Delta Region

CC:  
Donald Arey, Regional Superintendent, Department of Environment and Climate Change Land and Water, Beaufort Delta Region

GLWB

Bag Service 1, Inuvik, NT X0E 0T0



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	August 05, 2023
<b>Land Use Permit No.</b>	G20H006	<b>Previous Inspection:</b>	June 26, 2023
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	July 18, 2023
<b>Contractor:</b>	LJ's	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	James Creek Km 14.2		
<b>Current Stage of Operation:</b>	On-going		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected				
	<b>James Creek Km 14.2</b>				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				
Time as Permitted	A				

**Explanatory Remarks -**

James Creek Km 14.2:

During the inspection at James Creek maintenance camp on July 18, 2023 there were no concerns observed by the inspectors.

The site was clean and organized and in good condition.

Representative Signature

Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:  
**Figure 1**



**Figure 2**





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





# ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

