



Telephone: 867-678-8090 Ext. 24652

Fax: 867-777-2090

September 21, 2023

Department of Infrastructure
Bag service # 1
106 Veteran Way
Inuvik, NT X0E0T0

Attention: Allan Hamilton

File Number G21E001
Type of Operation HWY MAINTENANCE & OPERATIONS
Location KM 230

Dear Allan Hamilton,

An inspection of the above noted operation was conducted on September 15, 2023 by Resource Management Officer II Bradley Voudrach and Manager, Resource Management Jozef Carnogursky.

Enclosed is a copy of the Environmental Inspection Report. **Your attention to this matter is appreciated.**

If you have any questions, please contact me at 867-678-8090 Ext. 24652.

Sincerely,

Bradley Voudrach
Resource Management Officer II
Department of Environment and
Climate Change
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Environment and Climate Change,
Beaufort Delta Region

AlecSandra Macdonald, Regulatory Specialist, Gwich'in Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Department of Infrastructure	Permit Expiry Date:	June 27, 2026
Land Use Permit No.	G21E001	Previous Inspection:	August 30, 2023
Quarrying Permit No.		Inspection Date:	September 15, 2023
Contractor:		Subcontractor:	
Location(s) Inspected:	KM 230		
Current Stage of Operation:	Monitoring		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Operation				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				

Explanatory Remarks -

KM 230:

During the inspection the operation was completed for the Summer 2023 season. There was a Caterpillar Excavator parked within the pit that was used in the pit during construction. The Department of Environment and Climate Change would like to remind the Proponent (Department of Infrastructure) to submit the quantity of material removed from the pit no later than October 01, 2023 as per condition 12 of the Quarry Permit 2021QP0013.

MATTERS FOR FOLLOW UP

September 21, 2023:

- Obtain quantity of material removed from the pit during all construction activities

Representative Signature



Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

A photo of the excavator parked in the pit.



Figure 2

A general photo of the work area.





ENVIRONMENTAL INSPECTION REPORT

Figure 3

A small pile of material that was excavated but not removed from the pit.



Date:	September 15, 2023	Permit #:	G21E001	Page No:	3
-------	--------------------	-----------	---------	----------	---