

WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	Fort Liard A-01	Operator:	Paramount Resources
Location of Inspection:	Ft. Liard South Field	Access method:	Road access through BC (Liard Highway KM 122)
Site Contractor:	N/A	Status:	Suspended
Approval Info	ACW-2016-007	WID:	1858
Date of Inspection	Feb 11, 2017	H2S Site:	No

Summary of Inspection

Activity on site	Well Site cleared and snow covered		
Conditions	Satisfactory (Y/N)	Comments	
Site Access	Y		
Well Head Access	Y		
Well Signage	Y	Sign hanging on wellhead	
General Housekeeping	Y		
Other			

Additional Site Hazards:

Comments and Summary:

No facilities or current operations on site, just wellhead.

Documents Requested/ Collected:

Photos taken

Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.

Mischa Malakoe S-002 / Brian Heppelle S-001

Inspected By



Signature of OROGO Chief Safety Officer

2017-02-23

Date Signed