

WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	Fort Liard A-01	Operator:	Paramount Resources
Location of Inspection:	Ft. Liard South Field	Access method:	Road access through BC (Liard Highway KM 122)
Site Contractor:	N/A	Status:	Suspended
Approval Info	ACW-2016-007	WID:	1858
Date of Inspection	March 1, 2017	H2S Site:	No

Summary of Inspection

Activity on site	Well Site cleared and snow covered		
Conditions	Satisfactory (Y/N)	Comments	
Site Access	Y		
Well Head Access	Y	Wellhead laying on ground next to casing bowl	
Well Signage	Y		
General Housekeeping	Y		
Other			

Additional Site Hazards:

Comments and Summary:

Site operations idle, no work crew present.
 Tubing string laid down on racks near wellhead.
 Downhole abandonment operations completed February 2017.
 Casing bowl exposed and well scheduled to be cut & capped early march 2017.
 Sewage tank stored on site.

Documents Requested/ Collected:

Photos taken

Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.

Mischa Malakoe S-002 / Brian Heppelle S-001

Inspected By

2017-03-09

Date Signed



Signature of OROGO Chief Safety Officer